

ch-1 Measuring Instruments

Dt- 20-04-21

Measurement :-

The result of comparison of unknown quantity w.r.t. predetermined standard.

(OR)

The conversion of physical quantity into numerical quantity and it must be represented along with corresponding unit.

→ Unit represents characteristics of the measurement.

Condition :-

1. Result must be represented in numerical form along with corresponding unit.
2. Instrument used must be acceptable by the user.
3. Conversion from large to small quantity must be acceptable by the user.

Why :-

To have the existence in a practical world.

eg: Transformer

To design

To operate

To maintenance

To control

we require measurement.

Note :-

Measurement system is called as feed back.

control system → T/F

Methods of measurement

Direct methods :-

→ Unknown quantity is compared directly.

→ Draw backs :-

* Human being errors may be more.

* Practically not possible always practically not possible.
 * Practically this method is not preferred.
 always generally this method is not preferred.

Indirect method:-
 In this method some instruments are used in which some effects are produced to give the unknown value.

generally it is preferred.

Types of instrument:-
 mechanical instrument:-

- large size
- more weight
- more power consumption
- less portability
- suitable only for steady state applications.

Electronic Instrument:-

- size is less
- weight is less
- power consumption is low
- speed of operation is high
- suitable for both steady state and dynamic appl.


Electronic Instrument:-

- size is least
- weight is least
- power consumption is least
- fastest speed of operation.
- suitable for both steady state and dynamic operation.

Electrical
 Null type
 Deflection type

Null type instrument:-
 To indicate zero value

eg. - galvanometer
 These are of centre zero scale instruments or biased scale instruments.




each division = $\frac{0.000001}{100} = 0.00000001$

These are highly sensitive.

Deflection type instrument:-

These are used to measure the unknown quantity by the deflection of pointers.




Note:-

Though the null type instruments are more

sensitive than deflection type instruments, deflection type instruments are preferred to measure the unknown quantity.


Analog instruments:-

- these instruments work with analog signals.
- Analog signals are the signal which varies continously in finite no. of divisions.



Digital instruments:-
 These work with digital signals.

→ Digital signals are the signals which vary a distance step function by varying finite no. of division.



ERROR ANALYSIS

Error:-

Deviation of measured value from the true value is called error.

$E \rightarrow$ Error
 $A_t \rightarrow$ True value (actual value)
 $A_m \rightarrow$ Measured value

$E = A_m - A_t$

$A_m - A_t = 0 \Rightarrow A_t = A_m$
 $A_t - A_m = 0 \Rightarrow A_t = A_m$
 True value can be varied

$A_m = A_t \Rightarrow$ Direction is changed

* $A_m > A_t \Rightarrow E$ is +ve
 $A_m < A_t \Rightarrow E$ is -ve

E is true

Error

Static Dynamic

Absolute error $E_d = A_m - A_t$
 constant error $E_d = \delta A = A_m - A_t$
 static error correction

δA is denoted by δe
 IF δA is +ve, $\delta e = -ve$
 IF δA is -ve, $\delta e = +ve$

Relative static error: $\frac{\delta e}{A_t} = \frac{A_m - A_t}{A_t}$


δe is denoted by E_r
 δe is expressed as % of A_t

% $E_r = \frac{A_m - A_t}{A_t} \times 100$

It determines the quantity of the instrument.
 It is also called as limiting error / uncertainty.
 eg. δA is a relative error

A_t	$\frac{A_m - A_t}{A_t}$
1	10%
2	5%
8	1.25%
9	1.11%


↑ varies (variable errors)



Static characteristics of instruments
 These are the following static characteristics

- Accuracy
- Precision
- Drift
- Hysteresis
- Linearity
- Sensitivity
- Resolution
- Dead time and Dead zone


Accuracy: - The closeness with which an instrument reading approaches the true value



High accuracy

Guaranteed Accuracy Error (GAEE) → (6/A.F)

It is expressed w.r.t Full scale value (FSV)



6/A.F = 11%

A.F	6/A.F
2	30.1
3	20.1
5	12.1
8	7.5

Q. A 0-10 A ammeter has the GNE of 11%. Find the limiting error when 2A, 5A & 10A of supply is given.

Solⁿ Given, FSV = 10 A

GNE = 11%

% Limiting error = $\frac{FSV}{A} \times \% GNE$

When, $A_1 = 2A$

% L.E = $\frac{10}{2} \times 11\% = 55\%$

% L.E = $\frac{10}{5} \times 11\% = 22\%$

% L.E = $\frac{10}{10} \times 11\% = 11\%$


Note The limiting error is equal to the guaranteed accuracy error when true value (A.F) becomes Full scale value (FSV)

Precision: -

A prescribed value is either most repeated (or) most reproduced value

Repeated

Reproduced




Highly accurate instrument may be preferred
 precision confirms accuracy \rightarrow $\frac{\% \text{ error}}{\% \text{ FS}}$


3) Drift :-

\rightarrow It is the deviation.
 \rightarrow used when characteristic curve are plotted.

Note
 some of deviation is equal to zero then the instrument is provided with no drift.



4) Hysteresis :-
 Existing different property during loading and unloading




Hysteresis is due to mag. Inertia
 mag. saturation
 Residual flux

Hysteresis error is more because more deviation from loading to unloading
 Hysteresis error is less because less deviation from loading to unloading


5) Linearity :-

A system is said to be linear when o/p change is equal to i/p change




max. deviation of o/p line from ideal line $\times 100$

Linear scale
 Nonlinear scale




Note
 Proportional system may be linear. $\frac{\% \text{ error}}{\% \text{ FS}}$

* Linear systems are always proportional $\frac{y}{x}$
 * Proportional systems are always linear $\frac{y}{x}$




uniform / linear scale



non-linear / non-uniform

square law scale compressed at the beginning and spread out at the end.
 The scale which is changed at the beginning and spread out towards first scale.



same slope gradually

$$\% S = \frac{1}{L} \frac{\Delta y/P}{y/P}$$

range sensitivity / selection factor / scale factor

$$\% S = \frac{1}{L} = \frac{L/P}{y/P}$$

$$\% S = \frac{1}{24.5}$$

standard

$$\% S = \frac{1}{23}$$

$$\% S = \frac{1}{23}$$

Angle of sensitivity is $\tan^{-1} \left(\frac{\Delta y/P}{\Delta x/P} \right)$

* For linear instrument

$$\theta = \tan^{-1} (1) \rightarrow \theta = 45^\circ$$

Note


* For a linear system single sensitivity is defined and the angle of sensitivity is 45° only

* For a non-linear system multiple sensitivity can be defined.

* Resolution :-

* It is the smallest measurable IP change

$$R = \frac{\text{F.S.V.}}{\text{no. of divisions}}$$




Each div = 1000

Instrument 'R' has good Resolution

Note

Resolution is improved with no. of division, increased.

Dead time and Dead zone: -




Note: - Generally it is defined at origin

Dynamic characteristics: -

Speed of response: - the rapidly of an instrument to respond.

We prefer as high as possible speed of response

Measuring delay: - It is also called as delay



Types of errors: -

gross error: - these are the human being mistakes involving the reading, recording the value and calculating the required parameters of measurement

systematic error: -

Instrumental \Rightarrow (A) Repeated loading, and unloading (B) Error of instrument, zero error

Environmental \rightarrow Environmental change, observation \rightarrow parallax error

Random errors: - The error which can't be predicted (no cause)

Basic Instruments

Indicating

Eg: A, V, W

Recording

Eg: seismic graph

Integrating

Eg: energy meter

$E = \int P dt$

$\int A = \int Idt$

$= A \cdot h$ meter



Indicating Instruments: -





Deflecting Torque: - It is the torque produced in the instrument i.e required to move the pointer from the initial position

(Zero position)




Effects

Magnetic effect
Electromagnetic effect
Induction effect
Electrostatic effect



Force betⁿ PM and current carrying coil.

Force between coils of iron rod




Controling torque :-

→ It is the opposing torque produced by the instrument to have the steady state value.

At steady state position.

$$T_c = T_d$$



Spring control :-

$$T_c = k \theta$$

where $k =$ spring constant.

At steady state,

$$T_c = T_d$$


Linear/uniform scale

Advantages :-

→ uniform / linear scale.

→ It can be mounted either horizontally/vertically

→ gravity control



Balance weight

So, $T_c \propto \sin \alpha$

$$\Rightarrow T_c \propto \sin \alpha$$

At steady state position

non-linear / non-uniform scale


disadvantages

→ Non-linear / non-uniform scale.

Note: It should be mounted vertically only. Spring control method is generally preferred.

Damping torques

Defn. Weak & strong state of damping
 This is the torque produced in instruments, to stop the oscillation of the pointer about the zero's final steady state position.



So, due to which a torque is generated (final torque) (result)

Faraday's Law \rightarrow EMF eddy current bar

Ohm's Law \rightarrow Eddy

Lorentz's force \rightarrow a force (resulting force) (current carrying coil placed in mag. field)

Lenz's law \rightarrow The generated torque opposes the oscillating torque which is causing it, so finally a steady state position, the AI disc gets oscillated

Therefore flux will be cut by the AI disc, then emf will be induced (Faraday's law of electro-mag. induction). This emf is called as eddy emf.

\rightarrow Eddy = $\frac{R \cdot I}{dt}$ current is produced on the AI disc (ohm's law)

Now the current carrying AI disc placed in the magnetic field experiences mechanical force (Lorentz's law)

(This resultant force opposes the main cause (oscillating torque) (Lenz's law) & it is in opposite direction)

Therefore oscillation of pointer is stopped.

Conclusion

Order of effectiveness \rightarrow Eddy, Fluid, Air, Imp. order of preference \rightarrow Eddy, Air, Fluid

Moving Iron (MI) Instruments: in both's generation

The most common ammeters and voltmeters are of moving iron type.

Torque equation of MI Instruments: $T = I^2 \frac{d\theta}{dI}$

$\theta \rightarrow$ Deflecting torque

$d\theta \rightarrow$ Smaller deflection, $I \propto \sqrt{\theta}$

Mechanical work done in dt sec: $T \cdot d\theta$

Let, $I \rightarrow$ Initial current

\rightarrow Instrument inductance

If the current increases by dI , then the deflection changes by $d\theta$ and inductance by dL .

The voltage, $v = \frac{d\phi}{dt} (LI)$

Energy stored in 'i' sec = $\int \frac{dI}{dt} + I \frac{dL}{dt}$

$\int v dI = LI dI + I^2 dL$

Energy supplied in dt sec = $\frac{1}{2} LI^2 + d(I^2 L)$

So, energy stored in dt sec, $= \frac{1}{2} LI^2 + d(I^2 L)$

Energy stored in dt sec = $\frac{1}{2} LI^2 + d(I^2 L)$

neglecting the second and higher order terms,

Energy stored in dt sec = $LI dI + \frac{1}{2} d(I^2 L)$

From the conservation of energy

Electrical energy supplied = Increase in stored energy + work done

$\int LI dI + \frac{1}{2} d(I^2 L) = LI dI + \frac{1}{2} d(I^2 L) + I^2 dL$

$\frac{1}{2} I^2 dL = I^2 dL$

$I^2 dL = I^2 dL$

$I dL = I^2 \frac{dL}{dI}$

Integration from 0 to I

As $dL/dI = \text{constant}$

so, $\int I^2 dL = \frac{1}{2} I^2 L$

Controlling torque :-

The moving system is provided by control spring and deflecting torque T_d is balanced by controlling torque T_c

where, $k_c = \text{control spring constant N/m/rad}$

At the final steady state,

deflecting torque $(T_d) = \text{control torque } (T_c)$

$T_d = T_c$

$\frac{1}{2} k_c \theta^2 = \frac{1}{2} I^2 \frac{dL}{dI}$

Deflection $\theta = \frac{1}{\sqrt{k_c}} I^2 \frac{dL}{dI}$


i.e. deflection is proportional to square of rms value of operating current.

classification of moving iron instruments :-

moving iron instruments are of two types :-

- 1) Attraction type
- 2) Repulsion type

Attraction type :-



The above figure shows an attraction type instrument. The coil is flat and has a narrow slot like opening.

→ The moving iron is a flat disc or sector.

→ When the current flows through the coil a magnetic field is produced and moving iron moves from the weaker field outside the coil to the stronger field inside it i.e attracted inward.

→ The controlling torque is provided by gravity control method which is vertically moved.

→ Damping is provided by air friction with the help of a light aluminium piston (attached to moving system) which moves in a fixed chamber closed at one end at rest as shown in the figure.

Repulsion type :-

In this case, there are two vanes inside the coil, one is fixed and other movable. When current flows through the coil, there is a repulsion between two vanes resulting in the movement of moving vane.

Two different vane design are used:

a) Radial vane type
b) Co-axial vane type


Radial vane type

In this type vanes are radial & tripod from.

The fixed vane is attached to the coil and the movable one to the spindle of instrument.

Co-axial vane type

In this type of instruments the fixed or moving vanes are sections of co-axial cylinders.



→ The controlling torque is provided by spring.

→ The damping torque is produced by air friction, attraction type instrument.

→ The operating magnetic field in MI instrument is very weak so eddy current damping is not used

Note:-


Irrespective of direction of current in the coil of the instrument, the iron vanes are so magnetized that there is always a force of attraction in attraction type and repulsion in the repulsion type instruments. So MI instruments are unidirectional (or) unidirectional i.e they are independent of the direction in which the current passes. So MI instrument can be used for both ac and dc

Extension of range of moving iron instrument

Moving iron instruments can be built for a range up to 50A.

Shunts For MI Ammeter :-

When a shunt is used with an ammeter to extend the range the inductance of both the meter coil and the shunt must be considered along with their resistance.




The currents in the meter and shunt are in inverse ratio of their impedance.

$$\frac{I_{sh}}{I_m} = \sqrt{\frac{R^2 + (\omega L)^2}{(R_{sh})^2 + (\omega L_{sh})^2}}$$

$$= \frac{R_{sh}}{R} \sqrt{\frac{1 + \left(\frac{\omega L}{R}\right)^2}{1 + \left(\frac{\omega L_{sh}}{R_{sh}}\right)^2}}$$

→ The ratio of two currents depends on frequency Multipliers for MI voltmeters :-

The voltage range of MI instruments can be extended by the use of a series resistance/multiplier with the meter.



Let, R = Resistance of meter

Im = Meter current for full scale deflection

As angular frequency, out of phase the voltage drop across the meter for full scale deflection

$$V = I_m \sqrt{R^2 + (\omega L)^2}$$

Let, 'V' is the voltage to be measured.

$R_S \rightarrow$ Resistance of iron-inductive multiplier

Total resistance of ckt = $R_S + R_S$

Total inductance of ckt = $L + \omega^2 L^2$

Total impedance of ckt = $\sqrt{(R + R_S)^2 + \omega^2 L^2}$

The current in the meter, $I_m = \frac{V}{\sqrt{(R + R_S)^2 + \omega^2 L^2}}$

$\rightarrow V = I_m \sqrt{(R + R_S)^2 + \omega^2 L^2}$
multiplying power

Then the voltage

$$m = \frac{V}{V} = \frac{\sqrt{(R + R_S)^2 + \omega^2 L^2}}{\sqrt{R^2 + \omega^2 L^2}}$$

Comparison between Attraction and Repulsion type

instruments:-

\rightarrow Attraction type instruments have lower inductance as compared to repulsion type instrument.

\rightarrow Attraction type voltmeters are more accurate than repulsion type.

\rightarrow Repulsion type instruments are more suitable for economical production and nearly uniform scale.

Errors in moving iron instruments:-

There are two types of errors which occur

1) Errors which occur with both ac and dc

2) Errors which occur only with ac.

1) Errors which occur with both ac and dc

\rightarrow Errors with both DC and AC:-

Hysteresis Error:-

This error occurs as the value of flux density is different for the same current for ascending and descending values.

\rightarrow This error can be minimized by making the iron parts made so that they demagnetise themselves quickly (or) by making the iron parts at low flux density value.

\rightarrow Temperature Error:-


The temperature error in MI instruments arises due to temperature co-efficient of springs.

The error may be 0.02% per °C change in temperature.

In voltmeter, errors are caused due to self-heating of coil and series resistance. So the series resistance (R_S) should be made up of

stagger manganese with small temperature coefficient.

The value of series resistance (R_S) should be very large as compared to coil resistance (R) to minimize the errors due to self-heating.



9 stray magnetic field:-

The errors due to stray magnetic fields in fields other than the operating magnetic field can be minimized by using air iron casings, thin shield over working parts.

1) Errors with AC only:-


Frequency errors:-
Due to changes of reactance of working coil and eddy current setup in the metal parts of instrument.

2) Reactance of instrument coil:-
In case of voltmeter where an additional R_s is used in series with instrument coil, errors due to reactance occurs.

Let $R_i L$ → resistance and inductance of instrument
 R_s → series resistance
So, total current $I = \frac{V}{\sqrt{(R_i R_s)^2 + \omega^2 L^2}}$

As in AC instrument, deflection θ depends on the current through coil, the deflection at high frequency is less than low frequency.

→ This type of error can be reduced by using a capacitor 'C' across the series resistance R_s as shown in figure.



Eddy current:-

These errors are caused by the eddy currents induced in the iron parts of the instruments.

→ At low frequency, eddy current error increases and at high frequency this error is practically constant. Due to this AC instruments are not suitable for the frequencies above 125 Hz.

Advantages and disadvantages of AC instruments

if universal use:-
These instruments can be used for both AC & DC measurement of dielectric loss is rarely used for die application.

→ As the hysteresis effect causes large error in measurement of dielectric loss and current.

→ As hysteresis causes no problems for AC, AC instruments are widely used in industry for measurement of AC voltage and current.

1) less friction error:-
As the force-weight ratio is greater in AC, the frictional errors are quite small.

2) cheapness:-
As single type of moving element could cover the entire range to be measured, AC instruments are very cheap as compared to other instruments.

3) Robustness:-
Due to the simple construction and no current carrying moving parts, the instruments are robust.

Accuracy:-
These instruments are very accurate and precise within the limits of inductive grades.

Scale:-
These instruments are available with zero, circular, and other scales. The scale of these instruments is not uniform and graduated at lower end, so accurate readings are not possible.

Errors:-
These instruments suffer from errors due to hysteresis, frequency change and stray magnetic field.

Waveform errors:-
The non-linearity of B-H curve of iron result in the waveform error as the deflection torque is not exactly proportional to the square of current.

Difference betⁿ ac and dc calibration:-
There is a difference betⁿ ac and dc calibration due to the effect of inductance and eddy current when the meter is used for ac.

Problem The inductance of a moving iron instrument is given by, $L = (10 + 50 - \theta^2) \mu H$, where θ is the deflection in radian from zero position. The spring constant is $12 \times 10^{-6} N/rad$. Estimate the deflection for a current of 0.5 A.

Solⁿ Given that, $L = (10 + 50 - \theta^2) \mu H$
Spring constant, $k_t = 12 \times 10^{-6} N/rad$
current, $I = 0.5 A$
 $\theta = 9$

As we know deflection, $\theta = \frac{1}{k_t} \frac{T^2}{dL}$
 $\frac{dL}{d\theta} = (10 + 50 - \theta^2) \mu H$
 $= (60 + 50 - 20) \mu H/rad$
 $= 50 - 20 \mu H/rad$
 $= 5 \times 10^{-6} N/rad$

Putting the values eqⁿ we get,
 $\theta = \frac{1}{k_t} \frac{(15)^2}{12 \times 10^{-6} \times 5 \times 10^{-6}}$
 $= \frac{25}{24} (5 \times 10^6)$

$\Rightarrow 24\theta = 125 \times 10^6$
 $\Rightarrow 24\theta + 50 = 125$
 $\Rightarrow \theta = \frac{125}{24} = 5.2083 \text{ rad}$

Prob The inductance of a moving iron ammeter with a full scale of 90° at 1.5 A, is given by the expression $L = (60 + 40\theta - 4\theta^2 - \theta^3) \mu H$, where θ is the deflection in radian from zero position. Estimate the angular deflection of the pointer for a current of 1.0 A.

Given that, $L = (60 + 40\theta - 4\theta^2 - \theta^3) \mu H$
for $\theta = 90^\circ = \frac{\pi}{2} \text{ rad}$

Also, $\theta = \frac{1}{k_t} \frac{T^2}{dL}$
 $\frac{dL}{d\theta} = 40 + 40\theta - 8\theta^2 - 3\theta^3$
for, $\theta = \frac{\pi}{2} \text{ rad}$, $\frac{dL}{d\theta} = 40 - 3\left(\frac{\pi}{2}\right)^2$
 $= 20.03 \approx 20 \mu H/rad$

putting the value of $\frac{d\theta}{dI}$ in eqn (1)

$$\theta = \frac{1}{k_e} \frac{(1.5)^2 \times 10^6 \times 10^{-6}}{(1.5)^2 \times 10^6 \times 10^{-6}}$$

$$\Rightarrow k_e = \frac{10^{-6} \times 10^6}{\pi} = 10^{-6} \times 10^6 \times \frac{1}{\pi}$$

Now, for $I = 1A$.

$$\theta = \frac{1}{k_e} \frac{I^2}{dI} \frac{dI}{d\theta}$$

$$= \frac{1}{10^{-6}} \times \frac{(1)^2}{14.33 \times 10^{-6}} \times 10^{-6} = 30^\circ \times 10^{-6}$$

$$\Rightarrow 28.660 = 40 - 80 - 30^\circ$$


$$\Rightarrow 28.660 + 80 + 30^\circ = 40$$

$$\Rightarrow 30^\circ + 36.660 - 40 = 0$$

$$\theta = 1008 \text{ rad} \text{ or } 57.22 \text{ rad}$$

Permanent magnet moving coil instrument: -
 PMMC instrument is the most accurate for dc measurement.
 construction: -

(PMMC Instrument)



moving coil: -

The moving coil is wound with many turns of enameled (or) silk covered copper wire.

The coil is mounted on a rectangular aluminium former which is pivoted on jewel bearings.

The coils are freely in the field of permanent magnet.


Volmeter's coils are wound on metal frames and ammeter coils are wound on non-magnetic ferrite magnet systems.

Due to the development of materials like Alcon and Alnico having high coercive force, smaller magnet length is used in PMMC instruments.

The flux density in PMMC instruments varies from 0.1 wb/m² to 1 wb/m².

Concentric magnet: -

To obtain longer movement of the pointer and longer angular swing of the coil, concentric magnet assembly is used. It produces radial flux which extends over one or more. This type of construction is used for panel type instrument and some portable instruments.



(Concentric magnet)

Air coped coil:-


- In air coped coil, scale length is from 120° to 360° or even 360°.
- It gives leather resolution of reading for same scale range.

Open magnet system:-

Due to the development of ALNICO, the same magnet


itself behaves as core.

- The moving coil moves over the magnet.
- The active sides of the moving coil are located in the uniform radial field. belt? Pole piece and the steel yoke.



[Long scale moving coil instrument]

[Core magnet construction]



Advantages:-

- It is relatively unaffected by the external magnetic field.
- It eliminates the magnetic shunting effects.
- It eliminates the magnetic shunting in the former case.

Control torque:-

When the coil is supported between two jewel bearings the control torque is provided by two phosphorus bronze hair springs.

Damping Torque:-

Damping torque is produced by movement of aluminium former riding in the magnetic field of permanent magnet (Eddy current damping)

Pointer and scale:-

The pointer is carried by the spindle and moves over a graduated scale is of light-weight

[1.8.5]

Torque Equation :-

The deflecting torque (T_d)

Deflecting Force

$$F_d = BILr \sin \theta$$

As, $\theta = 90^\circ$

$$F_d = BIL \rightarrow \text{For one coil (turns)}$$

For N turns,

$$F = BILN$$

Now deflecting torque $T_d = Fd \times \text{displacement}$

$$= BILN \times S \left[\frac{S}{r} \right]$$

where, $r \rightarrow$ length of restoring spring coil

$b \rightarrow$ width of the coil turn

$$S_1, T_d = BILNl_2$$

$$T_d = BILNl_2 \left[\frac{AS}{r} \right]$$

where, $B =$ flux density wb/m^2

$I =$ Current

$N =$ No of turns and $A =$ Area of coil

$$Nl = T_d = BILNl_2$$

B, N, A are constants.

$$C_0, T_d \propto I$$

Controlling Torque -

The spring control provides the restoring

Torque, $T_c = k\theta$

For final steady state deflection,

$$T_c = T_d$$

$$\Rightarrow k\theta = BILNl_2$$

$$\Rightarrow \theta = \frac{BILNl_2}{k}$$


Again $B, N, A, k = \text{const}$

$$\theta \propto I$$

Ammeter shunts :-

When heavy currents are to be measured, the major part of the current is bypassed through a low resistance called shunt.

The resistance of shunt can be calculated by following



$R_m =$ Internal resistance of coil (Ω)

$R_{sh} =$ resistance of shunt (Ω)

$I_m = I_{FS} =$ Full scale deflection current (A)

$I_{sh} =$ shunt current (A)

$I =$ current to be measured (A)

As shunt resistance for in parallel with meter, voltage drop of shunt = voltage drop of meter.

$$\Rightarrow I_{sh} R_{sh} = I_m R_m$$

$$\Rightarrow R_{sh} = \frac{I_m R_m}{I - I_m}$$

Again, $I_{sh} = I - I_m$

$$S.O, R_{sh} = \frac{I_m R_m}{(I - I_m)}$$

$$\Rightarrow \frac{I - I_m}{I_m} - 1 = \frac{R_m}{R_{sh}}$$

$$\Rightarrow \frac{I}{I_m} = m = \frac{R_m}{R_{sh}}$$

$$\Rightarrow \frac{I}{I_m} = m = \text{multiplying power of shunt}$$

total current

meter current

$$\Rightarrow \frac{I}{I_m} = m = \frac{R_m}{R_{sh}}$$

$$\Rightarrow R_{sh} = \frac{R_m}{m-1}$$


General requirements of shunt

- Temperature Co-efficient of shunt and instrument should be low and same.
- Resistance of shunt should not vary with time.
- It should have a low thermal electromotive force with copper.
- It should carry current without excess heating temperature.

Note:-


- Manganin is used for shunt of d.c. instrument.
- Constantan is used for shunt of a.c. instrument.
- Effect of temperature changes on ammeter:-

To compensate the effect of temp change, a "swamping resistance" of manganin having a resistance 20-30 times of coil resistance is connected in series with the coil and a shunt of manganin is connected across the combination.



Multirange Ammeter

The current range of a d.c. ammeter can be extended by a number of shunts selected by a range switch. Such an ammeter is called multirange ammeter.



$R_{sh1} = \frac{R_m}{m_1 - 1}$
 $R_{sh2} = \frac{R_m}{m_2 - 1}$
 $R_{sh3} = \frac{R_m}{m_3 - 1}$
 $R_{sh4} = \frac{R_m}{m_4 - 1}$


$m_1 = \frac{I}{I_m}$
 $m_2 = \frac{I}{I_m}$
 $m_3 = \frac{I}{I_m}$
 $m_4 = \frac{I}{I_m}$

voltmeter multipliers:-

A series resistance connected across the meter to limit the current in voltmeter is known as multiplier.

The value of multiplier is calculated as below:-

$I_m = I_s = \text{full scale deflection current}$
 $R_m = \text{meter resistance}$
 $R_s = \text{multiplier resistance}$
 $V = \text{voltage across the meter}$



$V = \text{Full range voltage of instrument}$
 From the eqn,

$V = I_m (R_s + R_m)$
 $R_s = \frac{V - I_m R_m}{I_m}$

Factor for multiplier

$$M = \frac{V}{V_f} = \frac{I_m (R_m + R_s)}{I_m R_m}$$

$$M = 1 + \frac{R_s}{R_m}$$

$$M - 1 = \frac{R_s}{R_m}$$

$$\Rightarrow R_s = (M - 1) R_m$$


General requirement of multiplier:-

- Resistance should not change with time.
- Resistance change with temp should be small.
- Should be non-inductively wound for a.c. motor.

Effect of temp change in voltmeter:-

Multiplier resistance is made up of manganin having a negligible resistance temp. coefficient for compensation of temperature change.

multirange voltmeter:-



The multirange voltmeter can be constructed by connecting resistances in series with meter.

$$R_1 = (M_1 - 1) R_m$$

$$R_2 = (M_2 - 1) R_m$$

$$R_3 = (M_3 - 1) R_m$$

where, $M_1 = \frac{V_1}{V}$, $M_2 = \frac{V_2}{V}$, $M_3 = \frac{V_3}{V}$, $M_4 = \frac{V_4}{V}$

Errors in prime instruments:-

The main sources of errors in prime instruments are:-
 1. Weakening of permanent magnets due to ageing at temperatures effects.
 2. Weakening of springs due to ageing and temp effects.

3. Change of resistance of the moving coil with temperature.

magnets:-
 Magnets are aged by heat and vibration treatment which results in the loss of initial magnetism.

springs:-
 The weakening of springs with time can be reduced by careful use of material and pre-ageing during manufacture.

The weakening of magnets decreases the deflection force. Particular value of current but weakening of springs increases the deflection.

In prime i.e. increase of temperature reduces the strength of spring by about 0.04 percent and reduces flux density.

moving coil:-

The indication of prime instrument force constant current would decrease by 0.04 per cent rise in temperature.

But increase of prime voltmeter, due to the large series resistance of negative temperature coefficient eliminates the error due to temperature.

Advantages and Disadvantages of PMMC Instrument

Advantages:-

- The scale is uniformly divided.
- Few power consumption i.e. scales in degrees.
- Torque-weight ratio is high which gives a high accuracy.
- A single instrument can be used for many different current and voltage ranges by differential of shunts and multipliers.
- The large flux density we use as a coil/mv rate the errors due to stray magnetic field.
- Self-shielding magnets in case of core magnet construction is useful in aircraft and aerospace application.

Disadvantages:-


- These instruments are useful for only d.c. as when current reverses the torque reverses.
- The cost of these instrument is high than moving iron instruments.

Dynamometer type instruments:-

Electrodynamometer type instruments are used as wattmeters and ammeters both in the range of power frequencies and audio frequency range.

Operating principle:-

(Draw diagram from previous given photo)



→ In case of PMMC, torque is in one direction during one half cycle and opposite direction during the other half cycle. So the pointer would swing back and forth around the zero point.

→ If the direction of flux reverses each time current through the movable coil reverses, then unidirectional torque would be produced for both the and -ve half cycle construction:-

Fixed coil:-

- The field is produced by a fixed coil.
- The coil is divided into two sections to give uniform field near the center.
- The fixed coils are wound with fine wires supported by ceramic.

Moving coil:-

- The moving coil is wound either as a self-sustaining coil or else as a non-metallic former.

→ A metallic former cannot be used as it would produce eddy current by the alternating field, the control:- the controlling torque is provided by two control springs.


Moving system:-

- The moving coil is mounted on a aluminium spindle.
- The moving system also carries the counter weights and pointers.

Damping is provided by a pair of aluminium vanes attached to the spindle at the soft iron shieldings.

As the operating field produced by the fixed coil is nearly zero & coil which is very weak field, it is necessary to shield electrodynamic meter type instruments from the external strong magnetic fields.

Typical eqn of Electrodynamic Instrument:



[Ckt representation of electrodynamic instrument]

Let, i_1 = instantaneous value of current in fixed coil; A_1
 i_2 = instantaneous value of current in moving coil
 L_1 = self inductance of fixed coil, H
 L_2 = self inductance of moving coil, H
 M = mutual inductance self fixed coil and moving coil H .

Flux linkage of coil-1, $\phi_1 = L_1 i_1 + M i_2$
 Flux linkage of coil-2, $\phi_2 = L_2 i_2 + M i_1$

Electrical I/P energy = $\int i_1 d\phi_1 + \int i_2 d\phi_2$

$$As \Rightarrow L_1 = \frac{d\phi_1}{di_1} \text{ and } L_2 = \frac{d\phi_2}{di_2}$$

$$\Rightarrow L_1 dt = d\phi_1 \text{ and } L_2 dt = d\phi_2$$

Also, electrical O/P energy = $(L_1 di_1 + L_2 di_2) i_2$

$$= d\phi_1 i_1 + d\phi_2 i_2$$

$$= L_1 di_1 i_1 + L_2 di_2 i_2 + M di_1 i_2 + M di_2 i_1$$

Putting the value of $d\phi_1$ and $d\phi_2$ in equation of electrical input energy =

$$i_1 d(L_1 i_1 + M i_2) + i_2 d(L_2 i_2 + M i_1)$$

Energy stored in magnetic field.

$$= \frac{1}{2} L_1 i_1^2 + \frac{1}{2} L_2 i_2^2 + L_1 i_1 i_2 + L_2 i_2 i_1$$

$$= \frac{1}{2} d(L_1^2 i_1 + L_2^2 i_2 + 2 L_1 i_1 i_2 + 2 L_2 i_2 i_1)$$

According to principle of conservation of energy

Total electrical change in input energy = energy stored + mechanical energy

∴ mechanical energy = Total electrical change in energy - energy stored

Substituting eqn (1) From eqn (2) we get

Mechanical energy = $i_1 l_1 di_1 + i_1^2 dl_1 + i_1 i_2 dl_2 + i_1 i_2 dl_2 + i_1 i_2 dl_2 + i_2^2 dl_2 + i_2 i_1 dl_1 + i_2 i_1 dl_1 - (i_1 l_1 dl_1 + \frac{i_1^2}{2} dl_1 + i_2 l_2 dl_2 + \frac{i_2^2}{2} dl_2 + i_2 i_1 dl_1 + i_2 i_1 dl_1)$

$= i_1 i_2 dl_1 + i_2^2 dl_2 + i_1 i_2 dl_2 + i_1 i_2 dl_2 + i_2^2 dl_2 + i_1 i_2 dl_1 + i_2 i_1 dl_1 - i_1^2 dl_1 - \frac{i_1^2}{2} dl_1 - i_2^2 dl_2 - \frac{i_2^2}{2} dl_2$

$= i_1 i_2 dl_1 + i_2^2 dl_2 + i_1 i_2 dl_2 + i_1 i_2 dl_2 + i_2^2 dl_2 + i_1 i_2 dl_1 + i_2 i_1 dl_1 - i_1^2 dl_1 - \frac{i_1^2}{2} dl_1 - i_2^2 dl_2 - \frac{i_2^2}{2} dl_2$

$= i_1 i_2 dl_1 + \frac{i_1^2}{2} dl_1 + \frac{i_2^2}{2} dl_2 + i_1 i_2 dl_2 + i_1 i_2 dl_2 + i_2^2 dl_2 + i_1 i_2 dl_1 + i_2 i_1 dl_1 - i_1^2 dl_1 - \frac{i_1^2}{2} dl_1 - i_2^2 dl_2 - \frac{i_2^2}{2} dl_2$

As l_1 and l_2 are constant $dl_1 = 0$ & $dl_2 = 0$

So mechanical energy = $i_1 i_2 dl_1 + i_1 i_2 dl_2$ (19)

Let, $T_r =$ Instantaneous deflecting torque

∴ $dW =$ change in deflection

∴ mechanical energy = work done = $\int T_r d\theta$ (20)

so equating eqn (19) & eqn (20) we get,

$$T_r d\theta = i_1 i_2 \frac{d\theta}{dm}$$

$$\Rightarrow T_r = i_1 i_2 \frac{d\theta}{dm}$$

The average deflection of torque over a complete cycle

$$T_d = \frac{1}{T} \int_0^T T_r dt$$

let, $i_1 = I_{m1} \sin \omega t$

$i_2 = I_{m2} \sin(\omega t - \phi)$

where, $\phi =$ phase difference (phase angle) betⁿ i_1 & i_2

Then, $T_d = \frac{1}{T} \int_0^T I_{m1} I_{m2} \sin \omega t \sin(\omega t - \phi) dt$

$= \frac{d\theta}{dm} \frac{I_{m1} I_{m2}}{2T} \int_0^{2\pi} \sin \omega t \sin(\omega t - \phi) d\omega t$

Take

$$\cos(A+B) = \cos A \cos B - \sin A \sin B$$

$$\cos(A-B) = \cos A \cos B + \sin A \sin B$$

$$\cos(A-B) - \cos(A+B) = \cos A \cos B + \sin A \sin B - (\cos A \cos B - \sin A \sin B)$$

$$= \cos A \cos B + \sin A \sin B + \sin A \sin B - \cos A \cos B$$

$$= 2 \sin A \sin B$$

∴ $\sin A \sin B = \frac{1}{2} \cos(A-B) - \cos(A+B)$

similarely, $\sin A \cos B = \frac{1}{2} \cos(A-B) + \cos(A+B)$

putting the value of $\sin \omega t \sin(\omega t - \phi)$

$$\Rightarrow T_d = \frac{d\theta}{dm} \cdot \frac{I_{m1} I_{m2}}{2T} \int_0^{2\pi} [\cos \phi - \cos(2\omega t - \phi)] d\omega t$$

$$= \frac{d\theta}{dm} \cdot \frac{I_{m1} I_{m2}}{2T} \left[\cos \phi \int_0^{2\pi} d\omega t - \int_0^{2\pi} \cos(2\omega t - \phi) d\omega t \right]$$

$$= \frac{d\theta}{dm} \cdot \frac{I_{m1} I_{m2}}{2T} \left[\cos \phi (2\pi) - \frac{\sin(2\omega t - \phi)}{2} \int_0^{2\pi} d\omega t \right]$$

$$T_d = \frac{I_{m1} I_{m2}}{2} \cos \phi \frac{d\theta}{dm}$$

As $\frac{d\theta}{dm} = \frac{I_{m1}}{k_2} \beta \frac{I_{m2}}{k_1}$

$$T_d = \frac{I_{m1} I_{m2}}{2} \cos \phi \frac{d\theta}{dm} = \frac{I_{m2}}{\sqrt{2}}$$

where, I_{m1} & I_{m2} are rms value of current flowing through coils.

∴ At steady state position $T_d = T_e$

∴ $I_1 I_2 \cos \phi \frac{d\theta}{dm} = k_e \omega$

∴ Deflection $\theta = \frac{I_1 I_2 \cos \phi}{k_e} \frac{d\theta}{d\omega}$ (21)

Electrodynamometer Ammeter:-



In this case fixed coil and moving coils are connected in series.


So, $I_1 = I_2 = I$ and $\phi = 0$

So deflecting torque $T_d = I^2 \cos \theta \frac{d\phi}{d\alpha}$

Deflection $\theta = \frac{I^2}{k_e} \frac{d\phi}{d\alpha}$

The current through the moving coil should not exceed 100mA. Electrodynamic voltmeters:-

Deflecting torque $= I_1 I_2 \cos \phi \frac{d\phi}{d\alpha}$



In this case $I_1 = I_2 = I$ and $\phi = 0$

$T_d = \left(\frac{V}{Z}\right) \left(\frac{V}{Z}\right) \cos \theta \frac{d\phi}{d\alpha}$

$T_d = \frac{V^2}{Z^2} \frac{d\phi}{d\alpha}$

where, $V =$ voltage across the instrument.
 $Z =$ Impedance of the instrument circuit.

Deflection, $\theta = \frac{V^2}{k_e Z^2} \frac{d\phi}{d\alpha}$

Electrodynamometer, voltmeter range is 10 to 300V. Errors in electrodynamic meter instruments:-

There are various errors in dynamometer type instruments.

→ Low torque/weight ratio

→ High frequency

→ Eddy currents

→ External magnetic fields

→ Temperature change

→ Torque/weight ratio:-

As the flux linkage is very small the deflection torque is low.

→ A low torque/weight ratio indicates a heavy moving system, so the frictional losses is high, so frictional errors are high.

→ Frequency:-

The frequency error of dynamometer type instrument is very large due to the variation of self-inductance of coils with frequency in case of voltmeter.

Deflection $\theta = \left(\frac{V^2}{k_e Z^2}\right) \frac{d\phi}{d\alpha}$

Impedance, $Z = \sqrt{R^2 + \omega^2 L^2}$

→ Eddy current:-

The effect of eddy currents is to produce a torque seen moving coil and adjacent metal part.

→ The eddy current produces frequency error.

External magnetic fields:-

As the operating field is very weak, the external magnetic field interference is high. So shielding is required to avoid stray stray magnetic field.

Temperature changes:-

Self heating of coils produces errors.

To reduce the temperature errors, compensating resistors are used.

Advantages and Disadvantages of electro dynamometer instruments:-

Advantages:-

As all the coils are air-cored, these instruments are free from hysteresis and eddy current errors.

These instruments can be used up to frequency range of 5000 cycles.

These instruments can be used on both ac and dc.

Electrodynamometer voltmeters are most accurate type of ac voltmeter.

Disadvantages:-

The torque/weight ratio is the low, the sensitivity is also low.

Low torque/weight ratio gives increased fractional losses.

More expensive as compared to PMMC type.

Sensitive to overload and mechanical impact.


The operating magnetic field is weak but the large operating current results in large power consumption than PMMC.

Non-uniform scale. General frequency range is 0-125 Hz.

Rectifier Type Instruments:-

Rectifier type instruments are used for measurement of ac voltages and currents by using a rectifier element which converts ac to dc and then by using a dc meter (PMMC) to indicate the value of rectified ac.

These instruments are primarily used as voltmeter.



Basic arrangement of Rectifier instrument using a full wave rectifier (Ckt)

Half wave Rectifier type Instrument:-




When the voltage $V_{dc} = V$ is applied to ckt, the meter current $I_m = \frac{V}{R_s + R_m}$

When the voltage $V = V_m \sin \omega t = \sqrt{2} V_{rms} \sin \omega t$ is applied (where $V_m = \text{max/peak ac voltage}$)

$V = V_m \sin \omega t$
 $V_{rms} = \frac{V_m}{\sqrt{2}}$
 $V_m = \sqrt{2} V_{rms}$

→ The rectified unidirectional pulsating voltage produces a pulsating current and hence a pulsating torque.

→ The figure indicates the deflection corresponding to the average value of current which is dependent upon the average value of applied voltage.



Average value of voltage,

$$V_{av} = \frac{1}{2\pi} \int_0^{\pi} V_m \sin \omega t \, d(\omega t)$$

$$= \frac{V_m}{2\pi} \int_0^{\pi} \sin \omega t \, d(\omega t)$$

$$V_{av} = 0.318 V_m = 0.318 \times \sqrt{2} V$$

So, the current through the meter is


$$I_{av} = \frac{V_{av}}{R_m + R_s} = \frac{0.318 V_m}{R_m + R_s}$$

i.e. it produces a deflection that is 0.45 times that produced with de of equal magnitude V_r .


Full wave Rectifier type instrument

→ When a de voltage $V_{de} = V$ is applied to the rectifier the current through the meter, $I_m = \frac{V}{R_m + R_s}$ where, $V = V_{rms} = \frac{V_m}{\sqrt{2}}$ where, $V = V_{rms} = \frac{V_m}{\sqrt{2}} = \sqrt{2} V_{rms}$

Bridge Rectifier



Voltmeter using Full Bridge Rectifier.



is applied, then average voltage appearing across the meter

$$V_{av} = \frac{1}{\pi} \int_0^{\pi} V_m \sin \omega t \, d(\omega t)$$

$$= \frac{2V_m}{\pi} = 0.636 V_m = 0.9 V$$

So, the average current in the meter

$$I_{av} = \frac{0.9 V}{R_m + R_s}$$

Therefore the deflection with de 0.9 times that produced with de for same value of voltage V .

Sensitivity of Rectifier type instrument is

The de sensitivity of rectifier type instrument is $\frac{1}{\sqrt{2}}$ where I_{fs} is full scale

deflection, current.

→ for a half wave Rectifier type instrument, ac current is 0.45 times of dc current. So ac sensitivity $S_{ac} = 0.45 S_{dc}$

→ Similarly, for full wave rectifier type instrument, ac current is 0.9 times of dc, so ac sensitivity $S_{ac} = 0.9 S_{dc}$

Extension of Range of Rectifier Instrument as voltmeter

Let in a prime type rectifier instrument

$S_{dc} =$ de sensitivity

$V =$ voltage drop across prime meter

$V =$ applied voltage

$R_m =$ meter resistance, $R_d =$ Diode resistance

So for de operation

The series multiplier resistance for full wave

Rectifier

$$R = \left(\frac{V}{I_{FS}} \right) - R_m - R_d$$

$$= \frac{V}{I_{FS}} - R_m - R_d$$

$$R_s = \frac{V}{I_{FS}} - R_m - R_d$$

Similarly R_s for full wave Rectifier

$$R_s = \frac{V}{I_{FS}} - R_m - 2R_d$$

$$R_s = S_{dc} \cdot V \cdot R_m - 2R_d$$

For ac operation

$$R_s = S_{ac} \cdot V - R_m - R_d \quad (\text{Half wave})$$

$$R_s = 0.45 S_{dc} \cdot V - R_m - R_d$$

For full wave Rectifier.

$$R_s = 0.9 S_{dc} \cdot V - R_m - R_d$$

Factors affecting performance of Rectifier type instrument

Disadvantages / errors -

→ Effect of rectified wave form

→ Rectifier resistance

→ Temperature, changes

→ Rectifier capacitance

→ Decrease in sensitivity

Advantages -

→ The frequency range extends from about 20 Hz to high audio frequency.

→ These instruments have lower operating current for voltmeter than other instrument.

→ They have practically uniform scale for most ranges.

→ Their accuracy is about 1.5% loading effect.

loading effect is

The sensitivity of a rectifier type voltmeter is less than a d.c. voltmeter. So loading effect of ac rectifier voltmeter is more than of dc voltmeter.

The sensitivity of a rectifier type voltmeter is less than a d.c. voltmeter. So loading effect of ac rectifier voltmeter is more than of dc voltmeter.

of ac rectifier voltmeter is more than of dc voltmeter.

of dc voltmeter.

of dc voltmeter.

prob-1 A permanent magnet moving coil instrument has a core of dimensions $15\text{mm} \times 12\text{mm}$. The flux density in the air gap is $1.8 \times 10^{-5} \text{ wb/m}^2$ and the spring constant is $0.14 \times 10^{-6} \text{ N/m/rad}$. Determine the no. of turns required to produce an angular deflection of 90° when a current of 5mA flows through the coil.

Solⁿ Given that,

$A = 15\text{mm} \times 12\text{mm}$
 $= 15 \times 10^{-3} \text{m} \times 12 \times 10^{-3} \text{m}$
 $B = 1.8 \times 10^{-5} \text{ wb/m}^2$
 $K_s = 0.14 \times 10^{-6} \text{ N/m/rad}$
 $\theta = 90^\circ = \frac{\pi}{2} \text{ rad}$
 $I = 5\text{mA} = 5 \times 10^{-3} \text{ A}$

Let Final steady state, $\theta = \frac{\pi}{2} \text{ radian}$

$\Rightarrow \theta = \frac{K_d I}{K_s}$
 $\Rightarrow N = \frac{K_s \theta}{B I A}$
 $\Rightarrow N = \frac{0.14 \times 10^{-6} \times \frac{\pi}{2}}{1.8 \times 10^{-5} \times 5 \times 10^{-3} \times 15 \times 10^{-3} \times 12 \times 10^{-3}}$
 $\Rightarrow N = 136$

\therefore Multiplying power, $M = \frac{I}{I_m}$
 \therefore Resistance of shunt, $R_{sh} = \frac{R_m}{(M-1)}$

prob-2 Find the multiplying power of a shunt of resistance used with a galvanometer of 100Ω resistance. Determine the value of shunt resistance to give a multiplying power of 50.

Solⁿ Given that, $R_m = 100 \Omega$
 $R_{sh} = 200 \Omega$
 $M = 50$
 $I_m = 1\text{mA}$
 $I = 50\text{mA}$

Find R_{sh} for $M = 50$

$M = 1 + \frac{R_m}{R_{sh}}$
 $50 = 1 + \frac{100}{R_{sh}}$
 $R_{sh} = \frac{100}{50-1} = \frac{100}{49} = 2.04 \Omega$

prob-3 Design a multi-range dc milli-ammeter using a basic movement with an internal resistance $R_m = 50 \Omega$ and a full scale deflection current $I_m = 1\text{mA}$. The ranges required are $0-10\text{mA}$, $0-50\text{mA}$, $0-100\text{mA}$, and $0-500\text{mA}$.

Solⁿ (1) $0-10\text{mA}$ range. \therefore multiplying power, $M = 10$
 $\therefore R_{sh1} = \frac{R_m}{M-1} = \frac{50}{10-1} = 5.55 \Omega$

Resistance of shunt, $R_{sh1} = 5.55 \Omega$

(2) $0-50\text{mA}$ range, $M = 50$
 $\therefore R_{sh2} = \frac{50}{50-1} = 1.03 \Omega$

(3) $0-100\text{mA}$ range, $M = 100$
 $\therefore R_{sh3} = \frac{50}{100-1} = 0.506 \Omega$

(4) $0-500\text{mA}$ range, $M = 500$
 $\therefore R_{sh4} = \frac{50}{500-1} = 0.1 \Omega$

When $M = 50$, shunt resistance, $R_{sh} = \frac{R_m}{M-1} = \frac{50}{50-1} = 1.02 \Omega$

Problem 1 A moving coil instrument gives a full scale deflection of 10 mA when the potential difference across its terminals is 100 mV. Calculate, for the shunt resistance for a full scale deflection corresponding to 100 A.

→ The series resistance for full scale reading will be zero.
 → calculate the power dissipation in each case.
 given, meter current $I_m = 10 \text{ mA}$
 vol = 100 mV

meter resistance, $R_m = \frac{V_m}{I_m} = \frac{100 \text{ mV}}{10 \text{ mA}} = \frac{100 \times 10^{-3}}{10 \times 10^{-3}} = 10 \Omega$

→ shunt multiplying factor $n = \frac{I}{I_m}$
 $n = \frac{100}{10} = 10$

shunt resistance $R_{sh} = \frac{R_m}{n-1} = \frac{10}{10-1} = 1.11 \Omega$

power dissipation = $V_m I = 100 \times 10^{-3} \times 10 = 1 \text{ W}$

→ voltage multiplying factor $n = \frac{V}{V_m} = \frac{1000}{100 \times 10^{-3}} = 10$

series multiplier, $R_s = (n-1) R_m = (10-1) \times 10 = 90 \Omega$

power dissipation = $V_m I_m = (1000) \times (10 \times 10^{-3}) = 10 \text{ W}$

Prob 5 A meter has a speaker sensitivity. Meter A having range of 0-10V and multiplier resistance of 18kΩ or meter B with range of 0-300V and a multiplier resistance of 1.8kΩ.

→ both meter movements have a resistance of 2kΩ. Given that, $R_m = 2k\Omega$, $R_s = 18k\Omega$
 for meter A (0-10V) $R = R_m + R_s = 20k\Omega$

for meter B (0-300V) $R = R_m + R_s = 20k\Omega + 1.8k\Omega = 21.8k\Omega$

sensitivity of meter A = $\frac{1}{I_m} = \frac{1}{10 \text{ mA}} = \frac{1}{10 \times 10^{-3}} = 100 \Omega/\text{mA}$

for meter B (0-300V) $R = R_m + R_s = 20k\Omega + 1.8k\Omega = 21.8k\Omega$

sensitivity of meter B = $\frac{1}{I_m} = \frac{1}{10 \text{ mA}} = 100 \Omega/\text{mA}$

prob 6 The inductance of a 25 A electrodynamic ammeter changes uniformly at the rate of 0.0025 mH/degree. The spring constant is $10^{-2} \text{ N-m/degree}$.

Determine angular deflection at full scale.

→ Final steady deflection $\theta = \frac{T^2}{k} \cdot \frac{d\theta}{dI}$
 spring constant 'k' is given in N-m/degree and there, for, we must express (dθ/dI) in rad/dI deflection is to be found in degrees.

$\frac{d\theta}{dI} = \frac{0.0025 \times 10^{-6}}{10 \times 10^{-3}} = 0.25 \times 10^{-6} \text{ rad/A}$
 Deflection, $\theta = \frac{(25)^2}{10^{-2}} \times 0.25 \times 10^{-6} = 1.5625^\circ$

Prob 1 For a certain dynamometer, minimum deflection is at 60° and maximum deflection is at 30°. Find the deflecting torque produced by a deflection of 50mA corresponding to a deflection of 60°.

60° Rate of change of mutual inductance with deflection.

$$\frac{dM}{d\theta} = \frac{d}{d\theta} [1.6 \cos(\theta + 30^\circ)] = -1.6 \sin(\theta + 30^\circ) \text{ mH}$$

$$\left(\frac{dM}{d\theta}\right)_{\theta=60^\circ} = 1.6 \sin(90^\circ) = 1.6 \text{ mH/degree}$$

$$\text{Deflecting torque } T_d = \frac{1}{2} I^2 \frac{dM}{d\theta} = \frac{1}{2} (50 \times 10^{-3})^2 \times 1.6 \times 10^{-3}$$

... (faint handwritten notes and calculations)

Ch 3 Wattmeters and measurement of power pt-2

power in AC circuits! - The power taken by a load from a dc supply is given by the product of readings of an ammeter and a voltmeter when connected in the ckt as shown in figure.

v-A method Power = VI watt



$P_t = VI$
 $P_m = (V_m)(I_m)$
 $P = (V_t)(I_t)$

power in AC circuits! - The instantaneous power $p = v i$ where, $v =$ instantaneous voltage $i =$ instantaneous current

If both voltage and current wave are sinusoidal and current lags by ϕ phase by an angle ϕ , then $v = V_m \sin \omega t$ $i = I_m \sin(\omega t - \phi)$

$P = \text{Average power}$
 $P = \frac{1}{2} V_m I_m \cos \phi = \frac{1}{2} V_m I_m \cos(\alpha - \beta)$

$P = \frac{1}{2} V_m I_m \cos \phi = \frac{1}{2} V_m I_m \cos(\alpha - \beta)$

Average power over a cycle of AC is

$$P = \frac{V_m I_m}{2} \times \frac{1}{2\pi} \int_0^{2\pi} (\cos\phi - \cos(\phi - \theta)) d\omega t$$

$$P = \frac{V_m I_m \cos\phi}{2}$$

As $V_{rms} = \frac{V_m}{\sqrt{2}}$, $I_{rms} = \frac{I_m}{\sqrt{2}}$

$$P = V_{rms} I_{rms} \cos\phi$$

Previous Page: $V = A$

$$P_m = (V_m I_m) \sin\phi$$

$$= (V_e + V_a) (I_e)$$

$$= (V_e I_e + V_a I_e)$$

$$P_m = P_1 + V_a I_e$$

$$P_m \neq P_1$$

$$\rightarrow E \text{ is true}$$

$$\rightarrow P_m = P_1 + V_a I_e$$

$$= P_1 + I_e R_a I_e$$

$$= P_1 + I_e^2 R_a$$

$\rightarrow E$ is due to ammeter

\rightarrow suitable for a/c. R lead

the error is due to the instrument which is connected on the load side.

Electrodynamometer wattmeters:-


construction \rightarrow The design of electrodynamic wattmeter is similar to electrodynamic voltmeter and ammeter.

Fixed coils - The fixed coils or field coils are connected in series with the load, so carry the current in the circuit. So the fixed coils form the circuit of wattmeter.

moving coil - The moving coil is connected across the voltage and carries the current proportional to the voltage. So it is called "pressure coil" or "voltage coil" or P coil of wattmeter.

A high non-inductive resistance is connected in series with the moving coil to limit the current to a small value.

Both the fixed coil and moving coils are air cored. The moving coil is mounted on a pivoted spindle and entirely embraced by fixed current coils.



(Electrodynamometer type wattmeter)

Control: - Spring control is used for the instrument.

Damping: - Air friction damping is used as the operating magnetic field is very weak, so eddy current damping can not be used.

Scalers and pointers - Mirror type scales and knife edge pointers are used to remove the reading errors due to parallax.

Theory of Electrodynamic wattmeter:-

The instantaneous torque of an electrodynamic instrument is given by


$$T_i = i_1 i_2 \frac{d\phi}{d\alpha}$$

where i_1 & i_2 are instantaneous values of current in the two coils.



Circuit of electrodynamic meter wattmeter
Let, V, I are rms values of voltage and current to be measured.

Instantaneous value of voltage across R_L is, $v = V \sin \omega t$
As R_L is highly resistive, current $i_p = \frac{v}{R_p} = \frac{V \sin \omega t}{R_p}$



Instantaneous current $i_p = \frac{V}{R_p} \sin \omega t$
where, $I_p = \frac{V}{R_p}$ (rms) $\frac{V_p}{R_p}$ rms value of PC current.

If the current in the current coil lags the voltage in phase by an angle ϕ , the instantaneous value of current through cc is, $i_c = I_c \sin(\omega t - \phi)$
where I_c = rms value of cc current.

So, instantaneous torque,
 $T_i = I_c R_p \frac{d\theta}{dt}$
 $= I_c R_p \frac{d}{dt} \int \frac{1}{R_p} (V \sin \omega t - \phi) \sin \omega t dt$

$$= I_c \int V \sin \omega t \sin \omega t dt - I_c \int V \sin \omega t \cos \omega t dt$$

$$= \frac{1}{2} I_c V \int \sin 2\omega t dt - \frac{1}{2} I_c V \int \sin 2\omega t dt$$

Average deflecting torque,
 $T_d = \frac{1}{2\pi} \int_0^{2\pi} T_i dt$
 $= \frac{1}{2\pi} \int_0^{2\pi} I_c V \cos \phi - \cos \phi dt$

$$T_d = I_p I_c \cos \phi \frac{d\theta}{dt}$$

$$= \frac{V_p}{R_p} I_c \cos \phi \frac{d\theta}{dt}$$

where, $I_p = \frac{V_p}{R_p}$

controlling torque:
 $T_c = K_c \theta$
where, K_c = spring con.
 θ = final steady deflection.
At balance position,
 $T_d = T_c$

$$I_p I_c \cos \phi \frac{d\theta}{dt} = K_c \theta$$


$$\Rightarrow \theta = \frac{I_p I_c \cos \phi}{K_c} \frac{d\theta}{dt}$$

$$\theta = K \frac{d\theta}{dt} P$$

where, $K = \frac{1}{K_c R_p}$
 $V_p = V$
 $I_c = I$
where, P = power being measured
 $P = VI \cos \phi$


Errors in Electrodynamic wattmeter:-

Errors due to pressure coil self induction:-




e.o. \rightarrow low R_L , high L_c
p.c. \rightarrow high R_L , low L_c
So drop across cc. is less.
 $V_L = V_p$

Assumption 1:-
 PC is highly reactive $X_p(\phi_p) \approx 0$
 pure R_p




load 1:-
 I_p (only R_p) so in phase
 $I_e = I_c$
 $T_d = I_e I_p \cos \phi \frac{dm}{ds}$
 $= I_e \frac{V}{Z_p} \cos \phi \frac{dm}{ds}$ True power.

Now, $X_p \neq 0$



As less inductance
 for P.C. 50 Hz
 $\frac{R_p}{Z_p} = \cos \beta \Rightarrow Z_p = \frac{R_p}{\cos \beta}$
 $T_d = I_e I_p \cos(\phi - \beta) \frac{dm}{ds}$
 $= I_e \frac{V}{Z_p} \cos(\phi - \beta) \frac{dm}{ds}$
 $= I_e \frac{V}{R_p} \cos \beta \cos(\phi - \beta) \frac{dm}{ds}$ measured power



$P_d \propto I_e v \cos \phi$
 $\rightarrow P_m \propto I_e v \cos \beta \cos(\phi - \beta)$
 $\rightarrow P_m > P_d$
 $\rightarrow E$ is true

$P_m \times C.F. = P_d$, where $C.F. = \text{correction factor}$

$C.F. = \frac{P_m}{P_d} < 1$
 $C.F. = \frac{\cos \beta \cos(\phi - \beta)}{\cos \phi} < 1$


$\% E = \frac{P_m - P_d}{P_d} \times 100$
 $= \left(\frac{P_m}{P_d} - 1 \right) \times 100$
 $= \left(\frac{1}{C.F.} - 1 \right) \times 100$

After solving


$\% = \frac{1}{C.F.} - 1 \times 100$

loading load:-

$T_d = I_e I_p \cos \phi \frac{dm}{ds}$
 $= I_e I_p \cos \phi \frac{dm}{ds}$ True power.



$T_d = I_e I_p \cos(\phi + \beta) \frac{dm}{ds}$
 $= I_e \frac{V}{Z_p} \cos(\phi + \beta) \frac{dm}{ds}$
 $= I_e \frac{V}{R_p} \cos \beta \cos(\phi + \beta) \frac{dm}{ds}$ measured power



$P_d \propto I_e v \cos \phi$
 $\rightarrow P_m \propto I_e v \cos \beta \cos(\phi + \beta)$
 $\rightarrow P_m > P_d$
 $\rightarrow E$ is -ve

$\Rightarrow P_m \times C.F. = P_t$
 $\Rightarrow C.F. = \frac{P_t}{P_m} > 1$
 $= \frac{\cos \phi}{\cos \phi \cos(\phi + \beta)} > 1$


$\Rightarrow \% \epsilon = \frac{P_m - P_t}{P_t} \times 100$
 $= \left[\frac{P_m - P_t}{P_t} \right] \times 100 = \left[\frac{1}{C.F.} - 1 \right] \times 100$

$\% \epsilon = - (\tan \phi \tan \beta) \times 100$

Note
Error due to self inductance of potter coil is \rightarrow lagging load

$\% \epsilon = - (\tan \phi \tan \beta) \times 100$
 \rightarrow leading loads

Some Elimination of error due to self inductance




\rightarrow Error due to self inductance of potter coil can be eliminated by connecting a capacitor. ($C = 0.41 \frac{P_t}{V_c^2}$) in parallel with the resistance of the potter coil. (C showing the diagram)

$\frac{V_c \cdot A}{V \cdot A} \quad | \quad \frac{A \cdot V}{V \cdot A}$
 $R_m = R_t + I_c^2 R_a \quad | \quad R_m = R_t + I_c^2 R_a$
 $I_c^2 R_a = \frac{V_c^2}{R_v}$
 $R_m = R_t + \frac{V_c^2}{R_v}$
 $R_m = R_t + I_c^2 R_a$
 $R_m = R_t + I_c^2 R_a$

$\Rightarrow P_a R_v = \left(\frac{V_c}{I_c} \right)^2$
 $\Rightarrow P_a R_v = (R_v)^2$
 $\Rightarrow R_v = \sqrt{P_a R_v}$
 $R_c = \sqrt{R_a R_v}$

$3-\phi$ power
 $P_{3-\phi} = 3 \times I_{ph} \times V_{ph}$
 $= 3 \times I_{ph} \times I_{ph} \times R_{sc}$

1) Errors due to connection
 Me-short
 Le-short



$P_t = V_c I_c$
 $P_m = P_t \times C.F.$
 $= V_c I_c \times C.F.$
 $P_m = V_c I_c + V_c I_c$
 $= V_c I_c + V_c I_c$

$\rightarrow P_m = V_c I_c + (I_c^2) Z_{cc} Z_c$
 $\rightarrow P_m = V_c I_c + (I_c^2) Z_{cc}$
 $\rightarrow P_m = V_c I_c + V_c \cdot \frac{V_c}{2P_c}$

$\rightarrow P_m = V_c I_c + V_c I_c$
 $\rightarrow P_m = V_c I_c + V_c I_c$
 $\rightarrow P_m = V_c I_c + V_c I_c$

$\rightarrow P_m = V_c I_c + (I_c^2) Z_{cc} Z_c$
 $\rightarrow P_m = V_c I_c + (I_c^2) Z_{cc}$
 $\rightarrow P_m = V_c I_c + V_c \cdot \frac{V_c}{2P_c}$

\rightarrow e is due to current \rightarrow suitable for low R load
 \rightarrow suitable for high R load
 the error is due to the coil which is connected to the load.

\rightarrow pressure coil capacitance is due to inductance
 \rightarrow The pressure coil capacitance is due to inductance
 \rightarrow The effect of capacitance is opposite to the effect of inductance, so wattmeter reads high on lagging load.

4) Errors due to mutual inductance effects:-

→ Errors are caused due to mutual inductance between current and pressure coils of the watt meters.

→ These errors are quite low at power frequency and increases with the frequency frequency.

5) Eddy current errors:-

Eddy currents are induced in the solid metal parts and within the thickness of the conductor by alternating magnetic field of the current coil.

6) stray magnetic field errors:-

The relatively weak magnetic field of earth dynamometer wattmeter is affected by stray magnetic field resulting errors.

Laminated iron shields are used to reduce stray magnetic field error.

7) Errors caused by vibration of moving system:-

If the modulus frequency of moving parts like pointer, spring, is in resonance with the torque pulsation the moving systems produce vibration to avoid the vibration the modulus frequency of moving system is very much away from disturbance frequency of the system of wattmeter.

8) Temperature errors:-

The change in room temperature changes the resistance of the pressure coils and is affected of the springs.

To neutralize the effect, the pressure coil set is made up of copper and a resistance alloy having a negligible resistance temperature coefficient in the ratio 1:10.

Induction Type wattmeter and measurement of energy

Induction Type wattmeter:-

Induction type wattmeters are used for the measurement of power only in ac ckt's.

Construction:-

It consists of two laminated electromagnet wound with conductors known as shunt and series magnets.

The shunt magnet is known as shunt magnet consisting of three limbs.


The side limbs carry the windings and connected across the load.

These windings are excited by the current proportional to the voltage across the load so called voltage coils.

Series magnet:-

The lower electromagnet is connected in series with load, so known as series magnet.

It has two limbs and carries the windings called current coil and excited by the current proportional to load current.



A thin light weight disc made up of copper or aluminum is pivoted at the centre in the air gap between two electromagnets (shunt and series).

It is mounted with the help of spindle and pin is attached at the top of the spindle -

working of induction type wattmeter:-

A deflecting torque is produced on the disc due to the interaction of fields produced by the eddy current which causes to rotate the disc, than spring and pointer.

To provide controlling torque, spring control method is used.

Torque Equation

Let, v = voltage to be measured

I = current to be measured

ϕ = phase angle betⁿ v & I

ϕ_{se} = flux produced by series magnet.

ϕ_{sh} = flux produced by shunt magnet.

E_{sh} = emf induced in the disc by shunt magnet flux

E_{se} = emf induced in the disc by series magnet flux

I_{sh} = Eddy current in the disc caused by emf E_{sh}

I_{se} = Eddy current in the disc caused by emf E_{se}

Assuming the disc is fully resistive emf and eddy current will be in phase.

The phase difference betⁿ flux and eddy current will be 90°

The torque produce by the interaction of I_{se} and ϕ_{sh} is,

$$T_1 = k I_{se} \phi_{sh} \cos \phi \quad \text{--- (1)}$$


Similarly torque produce by I_{sh} and ϕ_{se} is,

$$T_2 = k I_{sh} \phi_{se} \cos(180^\circ - \phi) \quad \text{--- (2)}$$

So the resultant torque,

$$T_d = T_1 - T_2$$

$$= k I_{se} \phi_{sh} \cos \phi - k I_{sh} \phi_{se} \cos(180^\circ - \phi)$$



$$T_d = k I_{se} \phi_{sh} \cos \phi - I_{sh} \phi_{se} \cos \phi$$

As, $I_{se} \propto I$

$$\phi_{sh} \propto v \propto I_{sh}$$

$$T_d = k I^2 k_1 v \cos \phi \rightarrow k_2 v I \cos \phi$$

$$T_d \propto k v I \cos \phi$$

$$T_d \propto P \rightarrow \text{power}$$

Advantages:-

- The scale is uniform
- They provide good damping
- No effect of stray magnetic field.

Dis advantages:-

- Can be used only for ac power measurement.
- Low accuracy due to heavy moving system
- Error due to change in temperature
- Power consumption is more

Difference betⁿ electrodynamicmeter & induction type watt meter

Electrodynamometer type

Induction type

Can be used for both ac and dc power

used only for ac power

single pressure coil

Both current and pressure coils are supplied in to two parts.

pressure coil is the moving part to which pointer is attached.

A Aluminium disc the moving part to which pointer is attached.

Other Energy meters and measurement of Energy

→ Energy is the total power delivered or consumed over a time interval.

Energy = Power x time

$W = \int_0^t v i dt$

where, $v = \text{volt}$, $i = \text{Amperes}$, $t = \text{sec}$

→ so unit of energy is joule or watt second.

→ kilowatt-hour - energy consumed when power is delivered at an average rate of 1000 watt for one hour.

Meter constant:-

Meter constant is defined as the no. of revolutions made per kilowatt-hour (kWh)

Braking:-

→ The speed of the moving system is controlled by braking system.

→ Braking system is made up of permanent magnet (braking magnet) placed near the moving system which induces eddy currents in some part of the moving system.

→ The eddy currents produces a braking (retarding) torque which is proportional to the speed of moving system.

→ As eddy currents are produced in the aluminium disc, the moving system (disc) cuts through the field of permanent magnet.

EMF generated in the disc,

$\mathcal{E} = k_1 \phi \dot{n}$

where, $\phi = \text{Flux of permanent magnet (braking magnet)}$

$\dot{n} = \text{speed of rotation}$

$k_1 = \text{constant}$

When $r = \text{resistance of eddy current path}$,
 eddy current $I = \frac{\mathcal{E}}{r} = \frac{k_1 \phi \dot{n}}{r}$
 the braking torque (T_B) of flux of magnet & eddy current
 & effective radius R' of the disk

so, Braking torque,

$T_B = k_2 \phi I R$

$T_B = \frac{k_1 k_2 \phi^2 \dot{n} R}{r}$ (putting eqn 1)

$T_B = \frac{k_3 \phi^2 \dot{n} R}{r}$ (where $k_1 k_2 = k_3$)

→ If the radius of the disc $R = \text{constant}$.

then, $T_B = \frac{k_4 \phi^2 \dot{n}}{r}$ where, $k_3 R = k_4$

→ the moving system attains a steady speed when the driving torque is equal to the braking torque

braking torque at steady speed N is,

$T_B = \frac{k_4 \phi^2 N}{r} = k N$

where, $k = \frac{k_4 \phi^2}{r}$

→ At steady speed Braking torque = Deflecting torque

Theory of Induction type Energy meter:-

→ In induction type energy meter, two fluxes are produced by current flowing in the windings of current coil and potential coil of series magnet and shunt magnet respectively.

→ For two fluxes, two eddy currents are produced

→ so two torques are produced.

→ First flux interacting with eddy current produced by the second flux

→ second flux interacting with eddy current produced by the first flux

Let ϕ_1 and ϕ_2 be the instantaneous values of fluxes having a phase difference of β .
 $\phi_1 = \phi_m \sin \omega t$; $\phi_2 = \phi_m \sin(\omega t - \beta)$
 where, $\phi_m, \phi_{m2} = \text{max. value of fluxes.}$

$\phi_1 = \phi_m / \sqrt{2}$ } rms value of fluxes.
 $\phi_2 = \phi_m / \sqrt{2}$ }
 Flux ϕ_1 produces an emf in the disc by transformer action

$$E_1 \propto \left[-\frac{d\phi_1}{dt} \right] \propto \left[-\frac{d(\phi_m \sin \omega t)}{dt} \right]$$

$$\propto \left[-\omega \phi_m \cos \omega t \right] \propto \left[\phi_m \cos \omega t \right]$$

Let, $E = \text{rms value of emf } E_1$

$$E \propto \phi_m \propto \phi_1$$

Then the eddy current

$$I = \frac{E}{Z} \propto \phi_1$$

where $f = \text{frequency}$

$\phi_1 = \text{rms value of flux}$

$Z = \text{impedance of eddy current path.}$


\rightarrow If lags the voltage E by angle α ;

similarly $E_2 \propto \phi_2$ & ϕ_2

then eddy current

$$I_2 = \frac{E_2}{Z} \propto \phi_2$$

similarly I_3 lags E_3 by angle α'



Angle betⁿ I_1 & I_2 is $(90 - \beta + \alpha)$

Angle betⁿ I_2 and I_3 is $(90 + \beta + \alpha')$

$(90 + \beta + \alpha')$

Phasor diagram of induction type energy meter

\rightarrow Now average torque produced by the interaction of I_1 and ϕ_2 is

$$T_{d1} \propto I_1 \phi_2 \cos(90^\circ - \beta + \alpha)$$

$$\propto I_1 \phi_2 \cos(90^\circ - \beta + \alpha)$$

\rightarrow similarly average torque produced by the interaction of I_2 and ϕ_1 is

$$T_{d2} \propto I_2 \phi_1 \cos(90^\circ + \beta + \alpha')$$

$$\propto I_2 \phi_1 \cos(90^\circ + \beta + \alpha')$$

total deflecting torque

$$T_d = T_{d1} + T_{d2}$$

$$\propto \frac{\phi_2 \phi_1}{2} \cos(90 - \beta + \alpha) - \frac{\phi_2 \phi_1}{2} \cos(90 + \beta + \alpha')$$

$$\propto \frac{\phi_2 \phi_1}{2} \left[\sin(\beta - \alpha) + \sin(\beta + \alpha') \right]$$

$$\left[\text{Note, } \cos(90 - \beta + \alpha) = \sin(\beta - \alpha) \right]$$

$$= \cos(90^\circ - \theta) = \sin \theta$$

$$\propto \frac{\phi_2 \phi_1}{2} \left[\sin(\beta - \alpha) + \sin(\beta + \alpha') \right]$$

$$\propto \sin(\alpha + \beta) + \sin(\alpha - \beta) = 2 \sin \alpha \cos \beta$$

$$\propto \sin(\beta + \alpha) + \sin(\beta - \alpha) = 2 \sin \beta \cos \alpha$$

Deflecting torque, $T_d \propto \frac{\phi_1 \phi_2}{2} (2 \sin \beta \cos \alpha)$

$$T_d \propto \frac{\phi_1 \phi_2}{2} \sin \beta \cos \alpha$$

where, $\beta = \text{angle bet}^n \phi_1 \text{ and } \phi_2$

$\alpha = \text{angle bet}^n \text{ voltage and emf current (E \& I)}$

For max. torque,

α' should be nearly equal to 0°

$$\text{so } \cos 0 = 1$$

and β should be nearly equal to 90°

$$\text{so, } \sin 90^\circ = 1$$


Ch. 9
Energy meters and measurement of energy
dt. 15-07-21

Single phase induction type meter -

Construction :-

There are four main parts of the operating mechanism :-

- 1) Driving system
- 2) Moving system
- 3) Braking system
- 4) Registering system



Single phase energy meter

Driving system

The driving system of the meter consists of three electro magnets made up of silicon, steel laminations.

One of the electromagnet is excited by load current known as current coil carries current proportional to the supply voltage known as pressure coil.

Current electromagnet is also known as series

magnet and pressure electro-magnet is also known as shunt magnet.

Copper shading bands are placed on the complex limb of shunt magnet whose function is to bring the flux produced by the shunt magnet exactly in quadrature with the applied voltage.

Moving system :-


It consists of an aluminium disc mounted on the light alloy shaft which is perforated in the air gap belt series and shunt magnets.

Braking system :-

A permanent magnet placed near the edge of aluminium disc forms the braking system. The position of the permanent magnet is adjustable to adjust the braking torque.

Registering (counting) system :-

The function of a registering or counting system is to record continuously a number which is proportional to the revolution made by moving system and operation of single phase energy meter is



The supply voltage is applied across the pressure coil which is highly inductive, so the current I_p lags behind the supply voltage and lags proportionally to the supply voltage and lags it by a few degrees less than 90° (A).

→ I_p produces ϕ_p and induces eddy emf E_{ep} and current I_{ep} (Eddy current) in potential coil


→ which lags E_{ep} by angle α

→ similarly load current I_L flows through current coil and produces flux ϕ_s

→ ϕ_s proportional to load current and in phase with I_L

→ ϕ_s induces eddy emf E_{es} and induces current I_{es} in an angle α

→ I_{es} which lags E_{es} by an angle α



Let, V = applied voltage

I = load current

ϕ = phase angle betⁿ V & I

Δ = phase angle betⁿ supply voltage and pressure coil flux.

I_{sp} = pressure coil current

f = Frequency

Z = Impedance of eddy current path

α = phase angle betⁿ eddy emf and eddy current (phase diagram of single emf and eddy current phase induction type even)

(angle betⁿ E_{ep} and I_{ep} or E_{es} and I_{es})

ϕ_p = flux in potential coil

ϕ_s = flux in current coil

E_{ep} = eddy emf induced by flux ϕ_p

I_{ep} = eddy current due to flux ϕ_p

E_{es} = eddy emf induced by flux ϕ_s

I_{es} = eddy current due to flux ϕ_s

net deflecting torque

$T_d \propto \phi_1 \phi_2 \frac{1}{2} \sin \phi$

where, $\phi_1 = \phi_p$

$\phi_2 = \phi_s$

ϕ = angle betⁿ ϕ_p and ϕ_s

α = angle betⁿ emf and current

So, $T_d = k_1 \phi_p \phi_s \frac{1}{2} \sin(\Delta - \phi)$ cos α

But, $\phi_p \propto V$, $\phi_s \propto I$

So, $T_d = k_2 V I \frac{1}{2} \sin(\Delta - \phi)$ cos α

k_2 F, Z and α are constant,

$T_d = k_3 V I \sin(\Delta - \phi)$

→ T , N = steady speed, $T_B = k_4 N$ braking torque

At steady speed, the driving torque must equal to braking torque

$T_B = T_d$

$k_4 N = k_3 V I \sin(\Delta - \phi)$

$\sin \Delta = 90^\circ$

→ $k_4 N = k_3 V I \cos \phi$

→ $N = k_5 V I \cos \phi$

→ $N = k_6 \text{ Power}$

So, for registering the energy, speed of rotation N is proportional to power and Δ must be equal to 90°

total no of revolution = $N \Delta t$


= $k_7 (V I \cos \phi) \Delta t$

= $k_8 \text{ Power} \Delta t$

$N = k_9 \text{ energy}$

Long adjustment devices:

→ The meter wire register true energy when the angle Δ i.e. angle betⁿ supply voltage (V) and pressure coil flux (ϕ_p) is equal to 90° .




→ So a magnetic shunt circuit is introduced which by passes some portion of shunt magnet flux in the gap (ϕ_g) to make Δ exactly 90° (quadrature).

→ The required mmf is obtained from a lag coil which is located on the central limb of shunt magnet close to the disc gap.

→ For adjusting the mmf of lag coil, following arrangements are done.

1) Adjustable resistance:




→ The resistance of the circuit is altered to adjust the lag angle of flux ϕ_p .

→ When resistance is increased, the current

decreases, mmf in the lag coil decreases and value of lag angle Δ is decreased.

→ Similarly when resistance is decreased, the current and mmf of lag coil is increased, so value of lag angle Δ is increased.

→ The value of lag angle is adjusted to make $\Delta = 90^\circ$ by shading bands.



In this case copper shading bands are placed around the central limb of shunt magnet instead of lag coil with adjustable resistance.

→ When shading bands are moved upward more fluxes are linked which increases the induced emf, current and mmf, so lag angle Δ increases.


→ Similarly when shading bands are moved downward, flux linkage decreases, so emf, current, mmf also decreases and the lag angle Δ decreases.

→ The value of lag angle is adjusted to make $\Delta = 90^\circ$ light load (or) friction compensating.

→ Friction errors are more in case of light loads, so a small torque is required which acts in the direction of rotation and which is nearly equal to friction torque.


→ This torque is obtained by a small shading loop situated betⁿ the copper limb of shading magnet and the disc which is coil (a (H) + I).

Creep:-
The continuous rotation of meter when pressure coil is energised is called creeping. The major cause of creeping is overcompensation of friction, excessive voltage on pressure coil, vibrations and stray magnetic field.



To avoid creeping, two diametrically opposite holes are drilled on the disc, when the hole is under the edge of pole, the eddy current path in the disc will be disrupted and the creep will be stopped.

In some other cases, a small piece of spring is attached to the edge of the disc, so the force of attraction exerted by the brake magnet on the spring piece is sufficient to prevent creeping of disc.



→ magnetic shading
→ magnetic shading

→ Due to the rotation of disc continuously in the field of series magnet under load condition a dynamically emf is induced in the disc.

→ This dynamically induced emf creates braking torque which is proportional to the square of load current.

→ So when the load increases the self braking torque increases.

In order to minimize the self braking action at the full load speed of the disc is kept as low as possible i.e. nearly 40 rpm.

→ An overload compensating device i.e. a magnetic shunt is used which saturates and permeability decreases at overload.

voltage compensation:-
voltage variation causes error due to following reasons.

→ The relationship betⁿ shunt magnet flux and supply voltage is not linear.

→ The self braking due to dynamically induced emf in the disc by shunt magnet.

→ To minimize the voltage variation errors saturable magnetic shunt is used.

temperature compensation:-
When temperature increases:-

→ potential coil flux ϕ decreases and sag angle also decreases, shading band's decreases.

→ torque by shading band's increases.

→ Resistance of eddy current path increases, lag angle α of eddy current path decreases.

→ The increase in temperature causes the meter to run fast and register high.

Temperature compensation is done by using a temperature shunt on the brake magnet which is made up of special magnetic material like (mutemp) in which permeability decreases when temperature increases.