

Ac system has a number of advantages over d.c. system like;

- (i) The generation of A.C. is cheaper than that of D.C.
- (ii) A.C. machines are simple & do not require much alteration for their repair, maintenance during their use.
- (iii) AC can be easily be converted into DC.
- (iv) When AC is supplied at higher voltage in a long distance, the line losses are small compared to DC transmission.

These days 3-phase Ac system is being exclusively used for generation, transmission & distribution of power.


The machine which produce 3-phase power from mechanical power is called an alternator or synchronous generator. Alternators are the primary source of all the electrical energy we consume. These machines are the largest energy converters found in the world.

M.E \rightarrow AC energy


Basic Working Principle:-

An alternator operates on the same fundamental principle of electro magnetic induction as a d.c. generator i.e. when the flux linking a conductor changes, an emf is induced in the conductor. Like a d.c. generator, an alternator also has an armature winding & field winding. But there is one important difference b/w the two. In a d.c. generator the armature winding is placed on the rotor in order

to provide a way of converting voltages generated on the windings to a direct voltage at the terminals through the use of rotating commutator. The field poles are placed on the stationary commutator part of the machine. Since no commutator is required on the alternator it is usually more convenient advantages to place the field winding on the rotating part (rotor) of armature winding on the stationary part (stator). It is also convenient to place the field winding on the stator.



The stator consists of a cast iron frame which supports the armature core, having slots on its inner periphery for housing the armature conductors. The rotor is like a flywheel having alternate N & S poles fixed to its outer rim. The magnetic poles are excited (or magnetized) from direct current supplied by a small dc shunt generator which is excited from a dc source at 125 to 600 volts. In most cases or mounted on the shaft of the alternator itself. Because the field magnets are rotating, this current is supplied through two slip rings. As the exciting voltage is relatively small, the slip rings & brush gear are of light construction. Recently, brushless excitation system have been developed in which a 3-phase ac exciter, a group of rectifiers supply dc to the alternator. Here brushes, slip rings & commutator are eliminated.



current of E.M.F.

When the rotor rotates, the stator conductors (being stationary) are cut by the magnetic flux hence they have induced E.M.F. produced in them. Because the magnetic poles are alternating, they induce an emf & hence current flows in armature conductors, which first flows in one direction & then in the other. Hence an alternating emf is produced in the stator conductors whose frequency depends on the number of N & S poles (number past a conductor in one second) Right-hand Rule:

** Fleming's Right-hand rule gives, which direction the current flows. The right hand is held with the current flowing through the fingers, the thumb, index finger and middle finger making the thumb, index finger and middle finger mutually perpendicular to each other (at right angles), the thumb is pointed in the direction of the motion of the conductor relative to the magnetic field.

Stationary Armature:

The field winding of an alternator is placed on the rotor & is connected to dc supply through two slip rings. The 3-phase armature winding is placed on the stator. This arrangement has the following advantages;

- (i) The output current can be led directly from fixed terminals on the stator (or armature winding) to the load circuit, without having to pass it through brush contacts.
- (ii) It is easier to insulate stationary armature winding for high a.c. voltages which may have as high a value of 30kv or more.
- (iii) Only two slip rings are required for d.c. supply to the field winding on the rotor, since the exciting current is small, the slip rings and brush gear required are of light constructions.

iv) Due to simple construction of the rotor higher speed of rotating d.c. field is possible. This increases the output obtainable from a machine of given dimensions.

Construction of Alternator:-

An alternator has 3-phase winding on the stator & a dc field winding on the rotor.

(i) Stator:- It is the stationary part of the machine. In a dc machine, the outer frame (yoke) serves to carry the magnetic flux but in alternators, it

is not meant for that purpose. Here it is used for holding the armature stampings in positions. The armature core is supported by the stator & is built up of laminations of special magnetic iron or steel alloy. The core is laminated to minimise loss due to eddy currents. The laminations are stamped out in complete rings or in segments. The laminations are insulated from each other & have space between them, for allowing the cooling air to pass through.

(a) Rotor:-

Two types of rotors are used in alternators (i) Salient pole type. (ii) Smooth cylindrical type.


(i) Smooth cylindrical type:
The rotor carries a field winding which is supplied with direct current through two slip rings by a separate d.c. source.

(i) Salient pole type:-
In this type salient or projecting poles are mounted on a large cross-section steel frame which is fixed to the shaft of the alternator. The individual field pole windings are connected in series, in such a way that when the field winding is energised by the d.c. exciter, adjacent poles have opposite polarities.

Low & medium - speed alternators (120-1500 rpm) such as those driven by diesel engines or water turbines have salient pole type rotors due to the following reasons.
→ The salient field poles would cause an excessive windage loss if driven at high speed & would tend to produce noise.

→ The salient field poles would cause an excessive windage loss if driven at high speed & would tend to produce noise.

SALIENT POLE



→ Salient pole construction can not be made strong enough to withstand the mechanical stresses to which they may be subjected at higher speed.

Since a frequency of 50Hz is required, we must use a large no. of poles on the rotor of slow speed alternators. Low speed rotors always possess a large diameter to provide the necessary space for the poles. Consequently, salient pole type rotors have large diameters.


(ii) Smooth cylindrical type:-

In this type the rotor is made of smooth solid steel radax cylinder having a number of slots along the outer periphery. The field winding are embedded in these slots & are connected in series to slip rings through which they are energized by the d.c. exciter.


High speed alternators (1500 or 3000 rpm) are driven by steam turbines & are non salient type rotors due to following reasons:-

→ This type of construction has mechanical robustness & gives noiseless operation at high speed.

FIELD WINDINGS



→ The flux distribution around the periphery is nearly a sine wave & hence a better emf waveform is obtained than the salient pole type.




Since steam turbine run at high speed & a frequency of 50Hz is required, we need a smaller number of poles on the rotor of high speed alternators (also called turboalternators). We can use not less than 2 poles for this frequency the highest possible speed for a frequency of 50Hz is 3000 rpm of the next lower speed is 1500 rpm for a 4 pole machine. consequently turbo alternators possess 2 or 4 pole & have small diameter.

Relationship Between Speed & Frequency

In an alternator there exists a definite relationship between the rotational speed (N) if the rotor, the frequency (f) of the generated emf and the number of poles (P).

Consider the armature conductor marked N situated at the centre of $N/2$ pole rotating in clockwise direction, the conductor being situated at the place of maximum flux density will have maximum emf induced in it. When the conductor is in the interpole gap as at $N/2$ it has minimum emf induced emf because flux density is minimum there.

Again when it is at the centre of a pole it has maximum emf because flux density is maximum at maximum direction of the emf when conductor is over pole is opposite to that when it is over s-pole.



Obviously one cycle of emf is induced in a conductor when one pair of pole passes over it. Then other wavy the emf in an armature conductor goes through one cycle in average distance equal to twice the pole pitch.

Let p = total no. of magnetic poles.

N_s = speed of the rotor in rpm.
 f = frequency of generated emf in Hz.


Since one cycle of emf is produced when a pair of poles passes past a conductor, the no. of cycles of emf produced in one revolution of the rotor is equal to the no. of pairs of poles.
No. of cycles/revolution = $\frac{1}{2} p \times N_s$.
Frequency = $\frac{p}{2} \times \frac{N_s}{60}$

For example if speed is 1200 rpm and no. of poles is 4 then frequency = $\frac{4}{2} \times \frac{1200}{60}$ = 80 Hz.

1) Synchronous speed of generator represented by N_s . For a given alternator the no. of rotor pole is fixed. Therefore the alternator must run of synchronous speed to give an output of desired frequency. For this reason an alternator is sometimes called synchronous generator.

2) Alternator winding.

The windings for an alternator are much simpler than that of a d.c. machine because no commutator is used.



3) Pole distribution of an alternator. There are 12 slots. Each slot contains two coil sides that are placed in adjacent slots belonging to the same phase such as a_1 , a_3 or a_2 , a_4 constituting a phase belt. Note that in a 2-phase machine, phase belt is always 60° electrical. There are 12 total slots per each phase having four coils.

The four coils in each phase are connected in series so that their voltage add. There phase lead L connects to form a connection to the brushes via slip rings.

Winding factors!—

The armature windings of an alternator are distributed over the entire armature. The distributed winding produces nearly a sine wave from the heating is more uniform. The distribution of pitching of the coils affects the voltages induced in the cores. we shall discuss two winding factors:-

(b) Distribution Rate (Kd)

Distribution factor (k_d) =

卷之三

A winding with only one slot per pole perhaps is called a concentrated winding. In this type of winding, the emf generated /phase is equal to the arithmetic sum of the individual coil emf. (or) that phase. However if the coils /phase are distributed over several slots in space (Distributed winding) the emf in the coils are not in phase i.e phase difference is not zero but are displaced from each other by the slot angle α .

The angular displacement in electrical degrees b/w the adjacent slots is called slot angle. The emf phase will be the phasor sum of coil emfs.

K_d = $\frac{\text{emf with distributed winding}}{\text{emf with concentrated winding}}$

phasor sum of currents/phases


Ariphmetic sum of core emf / phase

Let, α = slot angle $\Rightarrow \frac{180^\circ}{\text{No. of slots/pole}}$

$\eta = \text{shots per pore per phase}$

Let $n=3$, the three core emf as phasors AB, BC & CD each of which is added of $\sqrt{3}$ times with a phase difference of 120° . The phasor sum of the core emfs subtends an angle of 0° .

$$K_d = \frac{5 \sin(90^\circ/2)}{5 \sin(90^\circ)}$$



卷之三

A cork whose sides are separated by one pole pitch is called a full pitch cork. With a full pitch cork the emf produced in the two coils sides agree in phase with each other & the resultant emf is the arithmetic sum of the individual emfs. However, the wave form of the resultant emf can be improved by making the cork pitch less than a pole pitch. Such a cork is called short pitch cork. The factor by which emf per coil is reduced is called pitch factor k.p.

$k_F = \frac{\text{emf induced in shorted pitch coil}}{\text{emf induced in full pitch coil}}$

The emf generated in the coils A & B in phase by an angle β if can be represented as $E_A \neq E_B$ respectively.

Since $E_A = k_F E_B$

SINGER EA. 1882. Wm. H. Morris

K_p = $\frac{E_{\text{mf}}}{E_{\text{ir}}} \cdot \frac{\text{produced in short pitch coil}}{\text{produced in full pitch coil}}$

$$\frac{2\overline{EF} \cos \beta / 2}{2\overline{EF}} = \cos \beta / 2$$

$$K_P = \cos \beta / 2$$

Q = Calculate the value of the distribution factor for a 3-phase 4-pole alternator having 36 slots.

$$\text{Ans} - \text{No. of slots/pole} = \frac{36}{4} = 9$$

$$\text{slot angle, } \alpha = \frac{180^\circ}{\text{No. of slots/pole}} = \frac{180^\circ}{9} = 20^\circ$$

$$\text{No. of slots/pole/phase, } n = \frac{9}{3} = 3$$

$$K_d = \frac{\sin(30^\circ/2)}{\sin(20^\circ/2)}$$

$$= \frac{\sin 30^\circ}{\sin 20^\circ} = 0.96$$

$$= \frac{\sin 30^\circ}{\sin 20^\circ} = 0.96$$

Q = calculate the distribution factor for a single phase alternator having slot/pole 1) when all the slots are wound & 2) when only four adjacent slots per pole are wound, the remaining slots being unwound.

- 1) when all the slots are wound.
 $n = 6$, slot angle $\alpha = 180^\circ/6 = 30^\circ$

$$K_d = \frac{\sin(30^\circ/2)}{\sin(15^\circ/2)}$$

$$= \frac{\sin(6 \times 30^\circ/2)}{\sin(6 \times 15^\circ/2)} = \frac{\sin 90^\circ}{\sin 90^\circ} = 0.644$$

If K_p & K_d are the pitch factor & distribution factor of the armature winding then

$$\text{E rms/phase} = 2.22 F K_p K_d F^2 \text{ volts}$$

Some times the factors (F) per phase conductor per phase are specified.

$$n = 4, \alpha = 30^\circ$$

$$K_d = \frac{\sin(30^\circ/2)}{\sin(15^\circ/2)}$$

$$\text{E rms/phase} = 4.44 K_p K_d F^2 \text{ volts}$$

$$= 550 \text{ V}$$

$$K_d = \frac{\sin(4 \times 30^\circ/2)}{\sin(30^\circ/2)}$$

$$= \frac{\sin 60^\circ}{\sin 30^\circ} = 0.837$$

EMF equation of an Alternator :-

$\text{let } Z = \text{No. of conductors or coils sides inserted per phase}$

$\phi = \text{Flux per pole in webers.}$

$P = \text{Number of rotor poles}$

$N = \text{Rotor speed in rpm}$
 $\text{In one revolution (i.e. } 60/\text{1}) \text{ sec. each stator conductor is cut by } P \text{ web. i.e.}$

$$d\phi = P\phi ; dt = 60/N$$

Avg. emf induced in one stator conductor:

$$= \frac{d\phi}{dt} = \frac{P\phi}{60/N} = \frac{P\phi N}{60} \text{ volts}$$

since there are 2 conductors in series per phase

$$\text{Avg emf/phase} = \frac{P\phi N}{60} \times 2 = \frac{P\phi^2 N}{60} \text{ volts.}$$

$$\text{Rms value of emf/phase} = \text{Avg value/phase} \times \sqrt{2} = \frac{120F}{P} \text{ volts.}$$

F = Factor of the emf/phase = Factor of the average value of emf/phase

$F = 2.22 F^2 \times 1.11 = 2.22 F^2 \text{ volts}$

Q - A 3-phase, 50 Hz star connected alternator has 18 conductors per phase of equal per pole. If 0.0593 wh. find (i) emf generated per phase in m.v. (ii) line frequency. Assume the winding to be fine pitched & distributed distribution factor to be 0.96.

$$\text{Ans (i) Generated emf/phase, } \mathcal{E}_{ph} = 2.22 k_p k_d 24^\circ$$

$$= 2.22 \times 180.96 \times 180^\circ \sin 24^\circ$$

$$= 1041.5 \text{ V}$$

$$\text{(ii) Line voltage, } \mathcal{E}_L = \sqrt{3} \mathcal{E}_{ph}$$

$$= \sqrt{3} \times 1041.5 = 1807.93 \text{ V}$$

Q - The armature of an 8 pole, 3-phase, 50 Hz alternator has 18 slots & 16 conductors/ slot. If flux of 0.01 wb is entering the armature from one pole, calculate the induced emf/ph.

Ans - If $k_p \neq k_d$ are not given assumed - 1

$$\text{Total no. of conductors} = 18 \times 16 = 180$$

$$\text{No. of conductor/phase, } Z = 180/3 = 60$$

$$\text{Induced emf/phase} = 2.22 \times k_p k_d \times 2 \times f \times \phi$$

$$= 2.22 \times 1 \times 60 \times 0.01 \times 50$$

$$= 266.4 \text{ v (ans)}$$

$$\text{Effect of harmonics on pitch of distribution factor, } k_d = \frac{\sin(30^\circ)}{\sin(20^\circ)}$$

Q - If the short pitch angle is α for the fundamental flux wave, then its value for different harmonics are:

$$\text{for 3rd harmonic} = 3\alpha$$

$$\text{Pitch Factor, } k_p = \cos \frac{\alpha}{2} \left[\begin{array}{l} \cos \frac{\alpha}{2} \\ \cos \frac{3\alpha}{2} \end{array} \right]$$

$$= \cos \frac{\alpha}{2} \left[\begin{array}{l} \cos \frac{3\alpha}{2} \\ \cos \frac{5\alpha}{2} \end{array} \right]$$

Similarly the distribution factor is also different for different harmonics. Its value becomes,

$$k_d = \frac{\sin \alpha/2}{n \sin \alpha/2}$$

where 'n' is the order of the harmonics,

$$n = 1 ; \quad k_d = \frac{\sin \alpha/2}{3 \sin \alpha/2}$$

$$n = 3 ; \quad k_d = \frac{\sin 30^\circ}{3 \sin 20^\circ}$$

c) frequency is also changed, $f_1 = 50/12$, 3rd harmonics, $f_3 = 3 \times 50 = 150 \text{ Hz}$, 5th harmonics, $f_5 = 5 \times 50 = 250 \text{ Hz}$

Q - A 3-phase, 16 pole alternator has a star connected winding with 144 slots & 10 conductors per slot. The flux per pole is 0.03 wb sinusoidally distributed & the speed is 345 r.p.m. calculate (i) the frequency of (ii) line induced emf.

$$\text{Ans - (i) Line induced emf, } f = \frac{PN}{120} = \frac{16 \times 3 \times 75}{120} = 50 \text{ Hz}$$

$$\text{(ii) slot angle, } \alpha = \frac{180^\circ}{10 \text{ of slots/pole}} = \frac{180^\circ}{144/16} = 20^\circ$$

$$\text{No. of slots/pole/phase, } n = \frac{144}{16 \times 3} = 3$$

$$\text{Distribution factor, } k_d = \frac{\sin(30^\circ)}{\sin(20^\circ)}$$

$$\text{for 3rd harmonic} = \frac{\sin 30}{3 \sin(20^\circ)} = 0.96$$

$$\text{No. of turns/phase, } T = \frac{144 N_0}{2 \times 3 \times 10} = 240$$

$$\text{Assume pitch factor, } k_p = 1$$

$$\text{Induced emf/phase, } \mathcal{E}_{ph} = 4.44 k_p k_d \times 240 \times 50 \times 0.03$$

$$= 4.44 \times 180.96 \times 240 \times 50 \times 0.03$$

$$= 1524 \text{ V}$$

$$\text{Induced line voltage, } E_L = \sqrt{3} E_{ph}$$

$$= \sqrt{3} \times 1534$$

$$= 2657 \text{ V (Ans)}$$

Q-A 3-phase, star connected alternator on open circuit required to generate a line voltage of 3600 V at 500 rpm. The stator has 3 slots per pole phase of 10 conductors per slot. Calculate

- The no. of poles if all are full flux per pole. Assume all the conductors per phase to be connected in series & the coils to be full pitch.

$$\underline{\text{Ans-}}(1) \quad f = \frac{P}{120} \quad \Rightarrow 50 = \frac{500 \times P}{120} = 12$$

$$\text{No. of slots/phase} = 3 \times 12 = 36$$

$$\text{No. of conductor/phase} = 36 \times 10 = 360$$

$$E_{ph} = \frac{3600}{\sqrt{3}}$$

$$\text{No. of slots/pole/phase}, n = 3$$

$$\alpha = \frac{180^\circ}{\text{No. of slots/pole}} = \frac{180^\circ}{36} = 20^\circ$$

$$\text{Distribution factor, } k_d = \frac{\sin(n\alpha/2)}{\sin(\alpha/2)}$$

$$= \frac{\sin(30^\circ/2)}{\sin(20^\circ/2)} = \frac{\sin 15^\circ}{\sin 10^\circ} = 0.95$$

core is short pitched by β , $\beta = 180^\circ - 140^\circ = 40^\circ$

$$k_d = \frac{\sin(n\beta/2)}{\sin(\beta/2)} = \frac{\sin(30^\circ \times 20^\circ/2)}{\sin(20^\circ/2)} = \frac{\sin 30^\circ}{\sin 10^\circ} = 0.95$$

$$\beta_p = \cos \beta/2 = \cos 20^\circ = 0.939$$

to calculate the pitch factor for a winding having 24 stator slots when the core span 5 slots.

Ans - Winding having 24 stator slots

pole pitch is 60 slots

$$\beta_p = \cos \beta/2 \quad [P=47]$$

$$E_{ph} = 2.22 k_p k_d 2f \phi$$

$$2080 = 2.22 \times 1 \times 0.939 \times 360 \times 50 \times \phi$$

$$\phi = 0.0543 \text{ wb.}$$

- Q-An alternator has 9 slots per pole. If each core span 8 slots. Pitcher, what is the value of the pitch factor?

$$\text{Ans - core pitch} = \frac{\alpha}{\beta} \times 180^\circ = 160^\circ$$

$$\text{core pitch} = \beta = 180^\circ - 160^\circ = 20^\circ$$

$$\text{pitch factor, } k_p = \cos \beta/2 = \cos 10^\circ = 0.985$$

Q-The stator of a 3-phase alternator has 9 slots per pole & carries a balanced 3-phase double layer winding. The coils are short pitched & the core pitch is 7 slots. Find the distribution factor & pitch factor.

$$\underline{\text{Ans - short pitch}} \quad \alpha = \frac{180^\circ}{\text{No. of slots/pole}} = \frac{180^\circ}{9} = 20^\circ$$

$$\text{No. of slots/pole/phase}, n = \frac{9}{3} = 3$$

$$\text{core pitch} = \frac{7}{9} \times 180^\circ = 140^\circ$$

$$k_d = \frac{\sin(n\alpha/2)}{\sin(\alpha/2)} = \frac{\sin(30^\circ \times 20^\circ/2)}{\sin(20^\circ/2)} = \frac{\sin 30^\circ}{\sin 10^\circ} = 0.95$$

$$\beta_p = \cos \beta/2 = \cos 20^\circ = 0.939$$

Alternator Reaction in Alternator

When an alternator is running at no load, there will be no current flowing through the armature winding. The flux produced in the air gap will be only due to the rotor armature. When the alternator is loaded, the air gap flux is changed from the no load condition.

The effect of armature flux on the flux produced by amperes turns (i.e. rotor) is called armature reaction.

Two things are worth noting about the armature reaction in an alternator. First the armature flux of the flux produced by rotor amperes turn rotate at the same speed i.e. synchronous speed in the same direction of the secondary. The modification of the flux in the air gap due to armature flux depends on the magnitude of stator current & on the power factor of the load.

It is the load power factor which determines whether the amperes flux distorts, opposes or helps the flux produced by the rotor-amperes turns. So we shall consider the three cases; i.e. (i) When load power factor is unity (ii) When load power factor is zero leading (iii) when load power factor is zero lagging.

(i) When load P.F. is unity:-



When load P.F. is unity, the effect of armature reaction is merely disturbed the main field.

(ii) When load P.F. is zero lagging:-

When pure inductive load is connected across the terminals of the alternator, current lags behind the voltage by 90° . This means that current will be maximum at zero emf vice versa. Now here armature flux is from right to left & field flux is from left to right. All the flux produced by armature current (i.e. armature flux) opposes the field flux & therefore weakens it. That means armature reaction is directly demagnetising. Hence, at zero P.F. leading the armature reaction weakens the main flux. This cause a reduction in generated emf.

(iii) When load P.F. is zero leading:-

When a capacitive load (zero P.F. reading) is connected across the terminals of the alternator, the current in armature load the induced emf by 90° obviously, the effect of armature reaction will be reverse, that for pure inductive load, thus armature



When alternator is no load since the armature is open circ, there is no stator current & hence due

to rotor current distributed symmetrically in the airgap. Since the direction of the rotor is assumed clockwise, the generated emf in phase is at 90° maximum, no armature flux is produced since no current flows in the armature winding.


When a resistive load (unity P.F.) is connected across the terminal of the alternator. As in the case of no load, the current is in the conductor under N-pole & out in the conductor under S-pole. Therefore, the armature flux is clockwise due to current in the top conductors & anticlockwise due to current in the bottom conductors. Armature flux is at 90° to the main flux & is behind the main flux. In this case the flux in the air gap is disturbed but not weakened.

Therefore at unity P.F. the effect of armature reaction is merely disturbed the main field.

(iii) When load P.F. is zero lagging:-

When pure. Inductive load is connected across the terminals of the alternator, current lags behind the voltage by 90° . This means that current will be maximum at zero emf vice versa. Now here armature flux is from right to left & field flux is from left to right. All the flux produced by armature current (i.e. armature flux) opposes the field flux & therefore weakens it. That means armature reaction is directly demagnetising. Hence, at zero P.F. leading the armature reaction weakens the main flux. This cause a reduction in generated emf.

flux now adds the main flux & the generated emf is increased. Here the armature flux is now in the same direction as the field flux & therefore strengthens it. This caused an increase in the generated voltage. Hence at zero p.f. reading the armature reaction strengthens



power factor values. the effect of armature reaction is practically disturbing & partially weakening for inductive load. For capacitive load, the effect of armature reaction is partially disturbing & partially strengthening. so that loads are generally inductive.


a) When the load p.f. is unity, the effect of armature reaction is wholly distorting.

b) When the load p.f. is less than unity, the effect of armature reaction is wholly demagnetizing.

When the load P.F. is zero reading, the effect of armature reaction is wholly magnetising.

(d) For intermediate value of load P.F. the effect of armature reaction is partially distorting & partially weakening. For inductive load, for capacitive load the effect is partly distorting & partly strengthening.

* In practice load on the alternator is generally inductive.



connected alternator supplying inductive load (say, P.F.). When the load on the alternator is increased (i.e. I_a is increased), the field excitation & speed being kept constant, the terminal voltage V of the alternator decreases. This is due to:


\rightarrow Armature leakage Reactance (X_L)! — When current flows through armature winding, flux is setup & it gives the windings self induction. This is called X_L . Therefore X_L drop which is also effective in reducing the terminal voltage.

\rightarrow Armature Reaction! — The load is generally inductive effect of armature reaction is to reduce the generated voltage. Since armature reaction results in a voltage effected in a effect. The quantity X_{AR} is called reactance of armature reaction. The values of X_{AR} is such that X_{AR} represents the voltage drop due to armature reaction.

The equivalent circuit of loaded alternator for one phase. All the quantities are per phase.
Here, E_0 = No load emf.

E = Load induced emf (it is the induced emf after allowing for armature reaction). It is equal to phase difference of $E_0 \times I_a X_R$.


V = Terminal voltage (it is less than E_0)



Synchronous Reactance (X_S): — The sum of armature reactance (X_L) & reactance of armature reaction (X_{AR}) is called Synchronous reactance X_S .

$$X_S = X_L + X_{AR}$$

[∴ Are one in perphase]




Synchronous Impedance, $Z_S = R_a + jX_S$

$$E_0 = Vt \tan \phi$$

$$= Vt I_a (R_a + jX_S)$$

Phasor Diagram of loaded Alternator! — Consider a Y-connected alternator supplying inductive load, the load p.f. angle being ϕ .



The phasor diagram shows off an open circuit of alternator for the case of inductive load. The armature current I_a lags the terminal voltage by p.f. angle ϕ . The phasor sum of all drops of phase sum of V & drops of I_a gives the load I_a & V gives the load induced voltage E . If E is the induced emf after allowing for armature reaction,

$$E = V + I_a (R_a + jX_L)$$

$$E_0 = E + I_a (jX_{AR})$$


The phasor sum of E & $I_a X_R$ gives the no-load emf E_0 . Note that the phasor diagram either the terminals voltage (v) or, aperature current, (I_a) may be taken as reference phasor.

Q - A 100 kVA, 3-phase, stator connected alternator has a rated line to line voltage of 3300V. The resistance & synchronous reactance per phase are 0.3 ohm & 4 ohm respectively. Calculate the line voltage of the emf generated at full load 0.8 pf lagging.

$$\text{Ans} - \text{pf of current } I_a = \frac{500 \times 10^3}{\sqrt{3} \times 3300}$$

$$= 87.5 A$$

I_a → taken as reference phasor from phasor diagram:



$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_a)^2}$$

$$\text{Now, } \cos \phi = 0.8 \quad \sin \phi = 0.6$$

$$\text{Line drop} = 87.5 \times 0.3 = 26.25 V$$

$$I_a R_a = 87.5 \times 0.3 = 350 V$$

$$\text{Terminal voltage} (v) = 3300/\sqrt{3} = 1905 V$$

$$E_0 = \sqrt{(1905 \times 0.8 + 26.25)^2 + (1905 \times 0.6 + 350)^2}$$

$$= 2152 \text{ volts}$$

$$\text{Line emf} = \sqrt{3} E_0 = \sqrt{3} \times 2152$$

$$= 3727 \text{ volt.}$$

Q - A 100 kVA, 230V, 3phase, stator connected alternator has a resistance of 0.3 ohm/phase & a synchronous reactance of 3.31 ohm/phase. Calculate the change of line voltage when the rated output of 100 kVA at power factor of 0.8 lagging is switched off.

Assume the speed of the exciting current to remain, unaltered.

Ans - Full load o/p current $I_a = \frac{100 \times 10^3}{\sqrt{3} \times 230}$

$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_a)^2}$$

$$\cos \phi = 0.8, \sin \phi = 0.6$$

$$I_a R_a = 251 \times 0.309 = 77.6 V$$

$$I_a X_a = 251 \times 3.31 = 831 \text{ volts}$$

$$\text{Terminal voltage, } v = 230/\sqrt{3} = 1328 V$$

$$= 1987 \text{ volts.}$$

$$\text{Line voltage} = \sqrt{3} E_0 = \sqrt{3} \times 1987 = 3441 \text{ volt}$$

$$\text{Change in line voltage} = 3441 - 2300 = 1141 \text{ volts.}$$

At a 60 kVA, 220V, 50Hz, single phase alternator has effective resistance of 0.07 ohm, find the voltage produced by the aperature when the alternator is developing rated current at a load p.f. of 0.8 unity, i.e., a 7 lagging pf load.


$$\text{Ans} - I_a = \frac{60 \times 10^3}{220} = 272.7 A$$

$$I_a R_a = 272.7 \times 0.07 = 19.04 V$$

$$I_a X_a = 272.7 \times 0.07 = 19.04 V$$

↑ unity p.f. current has been taken as the reference phasor

current has been taken as the



$$E_0 = \sqrt{(V + I_a R_a)^2 + (V + I_a X_a)^2}$$

$$= \sqrt{(220 + 4.3)^2 + (0)^2}$$

$$= 225.4 V$$

↑ 0.7 pf lagging

$$\cos \phi = 0.7$$

$$\sin \phi = 0.7$$

Assume the speed of the exciting current to remain, unaltered.

$$f = \sqrt{(v \cos \phi + \Omega a \sin \phi)^2 + (v \sin \phi - \Omega a \cos \phi)^2}$$

$$= \sqrt{(\nu \cos \phi + \tau_a R_a)^2 + (\nu \sin \phi + \tau_a h_c)^2}$$

= 234 works.

$$E = \sqrt{(\cos\phi + \sin\phi)^2 + \dots}$$

$$= \sqrt{(220 \times 7 + 4.3)^2 + (220 \times 7 - 19)}$$

208 works

resting on Heterogeneity. If so \rightarrow synchronous spread.


$\text{Re} \rightarrow$ effective resistance

Due to Armature reaction as already mentioned the sum of leakage reactance to acc. of voltage increases \propto current I_A

Where Z is the synchronous impedance of R_E


Determination of effective resistance of Aromatic! -

Armature resistance per phase can be measured directly by voltmeter - Ammeter method or by using wheatstone bridge.



DC resistance per phase can be measured directly by ammeter-voltmeter method as shown

DC resistance between pair of terminal with the DC field winding open is measured. The voltmeter reading divided by ammeter gives the value of resistance of two phases connected in series. So resistance of each phase, R_a will be equal to half the resistance measured, since the resistance under measurement is very low, it will be necessary to use a high current rheostat of adjust the current to about rated value. Synchronous impedance is determined from the open circuit & short circuit tests.



The connections for the open ckt test as shown in the above figure, with the armature winding circuit open, the machine is run at rated speed. The field is connected to a dc source in series with a shunt of an ammeter so that the field current is adjusted & noted. The field current is raised in suitable steps until the voltage per coil pair of terminals of the armature winding is somewhat above rated emf values of voltmeter for reading no load line voltage are noted. The open circuit voltages per phase & are obtained by dividing the voltmeter reading by

$$\text{What is } E_0 = I_{sc} Z_{eq}$$

$$Z_{eq} = \frac{E_0}{I_{sc}} = \frac{ACCL \text{ volt}}{4B \text{ (In Amp)}}$$

$$R_p = \sqrt{r_p^2 + R_e^2}$$

a - The effective resistance of a 220V, 40kW, 1-

Ans- short ckt current $I_{sc} = 200A$
open ckt voltage, $E_0 = 1160V$

$$Z_p = \frac{\text{short ckt voltage}}{\text{short ckt current}} = \frac{1160}{200} = 5.8\Omega$$

$$X_p = \sqrt{Z_p^2 - R_p^2}$$

Voltage Regulation!

The voltage regulation of an alternator is defined as the rise in voltage when full load is removed (field excitation & speed remaining the same) divided by the rated terminal voltage.

$$\% \text{ Regulation} = \frac{E_0 - V}{V} \times 100$$

P.F. reading

In the case of small machines, the regulation may be machines, the cost of finding the regulation by voltage direct reading becomes prohibitive. Hence other methods are used.

The methods are:

1) Synchronous impedance or

2) P.F. method.

If I_{fa} is the field current that gives the rated emf per phase represented by AC or AB gives the I_{sc}




Now the curve is drawn between E_f & I_f is known as open circuit characteristic.

2. Short - circuit Test:-

Diagram for short circuit test:

[Connection for short circuit test]

All the three phases are shorted. Since the three currents will be equal, only one of them need be measured so one ammeter is connected in only one of the three phase. Rheostat of sufficiently high ohmic value is inserted in the dc field coil to keep the current in the coil very low. The machine is run at synchronous speed. The reading of the ammeters connected in the field coil of armature ckt A_1, A_2 are noted. The short ckt characteristic is determined by plotting a curve between I_{sc} (short ckt current) & field current (I_f)



All these method require:-

- 1) Armature Resistance
- 2) ac characteristic
- 3) s.c. char. characteristic.

- Synchronous Impedance Method :-
- Consider a fixed current I_f . The ac voltage corresponding to this fixed current is E_f . When winding is short circuited the voltage is zero.

$E_f = I_f^2 Z_s$

$$\therefore Z_s = \frac{E_f (\text{open ckt})}{I_f (\text{short ckt})}$$


since R_a can be used as effective resistance

$$\therefore Z_s = \sqrt{Z_f^2 - R_a^2}$$

where $Z_f = E_0$

$$E_0 = \sqrt{(E_f R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

$$E_0 = \sqrt{(E_f R_a)^2 + (V \sin \phi + I_a X_s)^2}$$



$\% \text{ Reg} = \frac{E_0 - V}{V} \times 100$

To find the synchronous impedance of resistance of an alternator in which a given field current produces an armature current of 20A on short ckt & a generated emf of 50V on open ckt. The armature resistance is 0.71 ohm. To what induced voltage must the alternator be excited if it is to deliver a load of 100 A.p.f. of 0.8 lagging, with a terminal voltage of 200V.

first $Z_s = \frac{E_0^2}{I_a^2} = \frac{50^2}{20^2} = 12.5 \Omega$

$$X_s = \sqrt{Z_s^2 - R_a^2}$$

$$= \sqrt{12.5^2 - 0.71^2}$$

$$= 0.232$$

$$I_a R_a = 100 \times 0.71 = 100$$

$$I_a X_s = 100 \times 0.23 = 23 \text{ V}$$

$$\cos \phi = 0.8, \sin \phi = 0.6$$

$$E_0 = \sqrt{(V \cos \phi + R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

$$= \sqrt{(200 \times 0.8 + 10)^2 + (200 \times 0.6 + 23)^2}$$

$$= 222 \text{ V}$$

Q- From the following test records determine the voltage regulation of a 2000V, 1- ϕ alternator delivering a current of 100A at 0.8 p.f. leading P.F. of 0.71 lagging P.F. Test results : full load current of 100A is produced on short ckt by a field excitation of 0.5A. An emf of 500V is produced on open ckt by the same excitation. The armature resistance is 0.82 ohm. Inductance $L_a = 2000$, DC volt = 500V. DC current $I_{dc} = 100$

$$\% \text{ Reg} = \frac{500}{100} = 5\%$$

$$x_s = \sqrt{Z_s^2 - R_a^2} = \sqrt{5^2 - 0.82^2}$$

$$= 4.936 \Omega$$

$$T_a R_a = 100 \times 0.8 = 80 \text{ V}$$

$$T_a X_s = 100 \times 4.936 = 494 \text{ V}$$

$$\% \text{ unity } E_0 = \sqrt{(500 + 80)^2 + (494)^2}$$

$$= 213.8 \text{ V}$$

$$\% = \frac{E_0 - V}{V} \times 100 = 7\%$$

Q- 0.71 lagging

$$E_0 = \sqrt{(V \cos \phi + R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

$$= \sqrt{(2000 \times 0.71 + 80)^2 + (2000 \times 0.71 + 494)^2}$$

$$= \sqrt{(1500)^2 + (194)^2} = 2432 \text{ V}$$

$$\% = \frac{E_0 - V}{V} = \frac{2432 - 2000}{2000} \times 100 = 21.6\%$$

Q- 0.8 leading $- E_0 = \sqrt{(V \cos \phi + R_a)^2 + (V \sin \phi - I_a X_s)^2}$

$$= \sqrt{(2000 \times 0.8 + 80)^2 + (2000 \times 0.8 - 494)^2}$$

$$= 1680$$

$$\% = \frac{E_0 - V}{V} \times 100 = \frac{1680 - 1822.2}{1822.2} \times 100 = -9\%$$

Q - A full load current of 100A requires an excitation current of 3Amp. When a single phase 1200V alternator is short-circuited by an ammeter of resistance 0.01 ohm, the same excitation produces 350V. On S.C. the resistance of the armature is 0.5Ω. Calculate the regulation of the alternator at a 8% p.f reading.

Ans - Rated voltage, $V = 1200V$

$$g = 100A$$

$$R_e = 0.01\Omega$$

$$X_s = \sqrt{(R_e + \text{ammeter resistance})^2 + X_s^2}$$

(R)

$$= \frac{\text{o.e. volt}}{\text{o.e. current}}$$

$$= \frac{350}{100} \text{ (o.e.)}$$

$$X_s = \sqrt{3.5^2 - 0.5^2} = 3.5\Omega$$

at 0.8 leading p.f., $\cos\phi = 0.8$

$$\sin\phi = 0.6$$

$$E_0 = \sqrt{(V\cos\phi + jR_e)^2 + (V\sin\phi + jX_s)^2}$$

$$= \sqrt{(1200 \times 0.8 + j0.5)^2 + (1200 \times 0.6) + j100 \times 3.5)^2}$$

$$= 1.07V$$


$$\text{Voltage Regulation} = \frac{107V - 1200}{1200} \times 100$$

$$= -10.25\%$$

a - find the synchronous impedance of reactance of a single phase alternator in which a given fixed current produces an armature current of 250A, on S.C. $\cos\phi = 0.5$. Calculate emf of induction open circuit. The armature resistance is 0.01 ohm. Calculate the terminal p.f. at a lagging p.f. of 0.8 if switch off.

Ans - $R_e = 0.01\Omega$, $X_s = 0.5\Omega$, $V = 1200V$, $\cos\phi = 0.5$, $\sin\phi = 0.8$

In this method, the data determined from open ckt test are utilised.



from the characteristic curve it is determined to give rated voltage V when no load, neglecting armature resistance R_a drop of field current I_f is determined to cause short ckt current equal to full load current on short ckt. The field current I_f balances the impedance drop in addition to armature reactance on full load. But since R_a is usually very small & X_L is also small for low voltage on short ckt, so impedance drop can be neglected. Hence P.F. on short ckt is almost zero. Asymmetry of the field ampere turns are used effectively to overcome the armature reaction.

This method of determination of synchronous reactance is known as optimistic method since it gives value lower than actual value. The reason is that the excitation to overcome armature reaction is determined on unsaturated part of saturation curve.

V-curves for Alternator:-

The graph betw. armature current (I_a) of field current (I_F) of an alternator for a constant output power is called its V-curve. The curve is so called because it is V-shaped.



$I_F \rightarrow$

parallel operation of Alternator!

It is rare to find a 3-ph alternator supplying its own load independently except test conditions. In practice every large number of 3-phase alternators operate in parallel because the various power stations are interconnected through the national grid. Therefore the capacity of any single alternator is small compared with the total interconnected capacity. For this reason the performance of a single alternator is unlikely to affect appreciably the voltage & current & frequency of the whole system.

An alternator connected to such a system is said to be connected to infinite bus bars. Such busbars are those having constant voltage, constant frequency busbars. The operation of connecting an alternator to the infinite busbar is known as paralleling with the infinite busbar.

Advantages of parallel operation of alternators:-

1) Continuity of service:— If one alternator fails the continuity of supply can be maintained through the other healthy units. This will ensure uninterrupted supply to the consumers.

2) Efficiency:— The load on the power system varies during the whole day, being minimum during the night hours. Since alternators operate most efficiently when delivering full load this permits the efficient operation of the power system.

3) Maintenance of Reserve:— It is often desirable to carry out routine maintenance or repair of one or more units. For this purpose, the desired unit can be shut down for the continuity of supply is maintained through the other units.

Conditions for paralleling alternator with infinite busbar

The proper method of connecting an alternator to the infinite busbar is called synchronizing. In order to connect an alternator safely to the infinite busbar the following conditions are met:-

- i) The terminal voltages (r.m.s value) of the incoming alternator must be same as busbars voltage.
 - ii) The frequency of the generated voltage of the incoming alternator must be equal to the busbar frequency.
 - iii) The phase of the incoming alternator voltage must be identical with the phase of the busbars voltage.
- iv) The phase sequence of the voltage of the incoming alternator should be the same as that of the busbar.

Methods of synchronisation:

The method of connecting an incoming alternator safely to the live busbar is called synchronising.

The equality of the voltage between the incoming alternator & the busbars can be easily checked by voltmeter.


The phase sequence of the alternator & the busbars can be checked by a phase sequence indicator.

Difference in frequency of phase of the voltage of the incoming alternator & busbar can be checked by two methods -

(i) By three lamp method.

(ii) By synchroscope.


i) Three lamp method:



incoming alternator

In this method of synchronising, the lamps L_1 , L_2

are connected as shown in above. The lamp L_1 is straight connected between the corresponding phases of the other two phases, the lamp L_2 is connected between L_1 & L_3 (i.e., L_1 , L_2 , L_3). When the frequencies of the voltage of the voltage of the busbars the



A synchroscope is an instrument that indicates by means of a revolving pointer, the phase difference & frequency difference b/w the voltage of the incoming alternator & the busbars.

If it is essentially a small motor, the field being supplied from the busbar through a potentiometer attached to the rotor. When the incoming alternator is running fast frequency of the incoming alternator is higher than that of the busbars, the rotor & hence the pointer moves in the clockwise direction. When the alternator is running slow i.e. the frequency of the alternator is lower than that of the busbar, the pointer moves anticlockwise direction. When the frequency of the alternator is equal to that of the busbar, no torque acts on the rotor of this pointer points vertically upward. It indicates the correct instant for connecting the alternator to the busbars. The synchroscope method is superior to the lamp method. Because it not only gives a true indication but the adjustment should be less.

at alternator should be less.

Hunting

Sometimes an alternator will not operate satisfactorily with others due to hunting.

→ If the driving torque applied to an alternator is pulsating such that produced by diesel engine, the alternator rotor may be pulled periodically a head or behind its normal position as it rotates. This oscillation action is called hunting. To lessen this machine, hunting is reduced by providing damper winding.

It consists of short cut copper bars embedded in the pole faces.



When hunting occurs, there is shifting of armature flux across the pole face, thereby induced current opposes the action that produced the hunting action, is opposed by the flow of occurs.

NOTE: * Hunting generally occurs in alternators driven by engines because the driving torque of engines is not constant. * In cylindrical rotor machines the damper winding are generally not used. It is because the ~~constant~~ damping.

Introduction

The 3- ϕ induction motors are the most widely used electric motors in industry. They run at essentially constant speed from no-load to full load.

3- ϕ induction motor

→ Like any electric motor, a 3- ϕ induction motor has a stator and a rotor.

StatorRotor

→ The stator carries a 3- ϕ winding (called stator winding) while the rotor carries a short circuited winding (called rotor winding).

→ Only the stator winding is fed from 3- ϕ supply. The rotor winding derives its voltage and power from the externally energised stator winding through electromagnetic induction and hence the name.

→ The induction motor may be considered to be a transformer with a "rotating secondary" and it can, therefore, be described as a "transformer type" a.c. machine in which electrical energy is converted into mechanical energy.

Advantages:-

→ It has simple and rugged construction.

→ It is relatively cheap.

→ It requires little maintenance.

→ It has high efficiency and reasonably good power factor.

Disadvantages:-

→ It is essentially a constant speed motor and its speed cannot be changed easily.

→ Its starting torque is inferior to dc shunt motor.

Construction:-

→ A 3- ϕ induction motor has two main parts:-

(i) Stator and (ii) Rotor

→ The rotor is separated from the stator by a small airgap which ranges from 0.5mm to 1.5mm, depending on the power of the motor.

1) Stator:-

→ It consists of a steel frame which encloses a hollow cylindrical core made up of thin laminations of silicon steel to reduce hysteresis and eddy current loss.

→ A number of evenly spaced slots are provided on the inner periphery of the laminations.

→ The insulated conductors are placed in the stator slots and are suitably connected to form a balanced 3- ϕ star or delta connected circuit.

→ Rotor:- The rotor, mounted on a shaft, is a hollow laminated core having slots on its outer periphery.

(ii) squirrel cage type (iii) wound type

i) Squirrel cage type:-


→ It consists of a laminated cylindrical core having parallel slots on its outer periphery, one copper or aluminium bar is placed in each slot.

→ All these bars are joined at each end by metal rings called end rings.

→ This forms a permanently short-circuited winding which is indestructible.

→ Those induction motors which employ squirrel cage are called squirrel cage induction motors.


→ Motor of 3- ϕ induction motors use squirrel cage rotor as it has remarkably simple and robust construction enabling it to operate in the most adverse circumstances.



2) Wound Type Rotors:-

→ It consists of a laminated cylindrical core and carries a 3- ϕ winding similar to the one on the stator.

→ The rotor winding is uniformly distributed in the slots and is usually star-connected.



Rotating Magnetic Field Due to 3- ϕ currents:-

→ When a 3- ϕ winding is energised from a 3- ϕ supply, a rotating magnetic field is produced.

→ This field is such that its poles do not remain in a fixed position on the stator but go on shifting their positions around the stator. For this reason, it is called a rotating field.



→ The 3- ϕ I_x , I_r and I_z are energised from a 3- ϕ source and currents in these phases are indicated as I_x , I_r and I_z .

* Fluxes produced by these currents are given by:

$$\phi_x = \phi_m \sin \omega t$$

$$\phi_r = \phi_m \sin (\omega t - 120^\circ)$$

$$\phi_z = \phi_m \sin (\omega t - 240^\circ)$$



→ We shall now prove that this 3- ϕ supply produces a rotating field of constant magnitude equal to $1.5\phi_m$ at instant $t=0$.

Therefore, the three fluxes are given by
 $\phi_x = 0$; $\phi_r = \phi_m \sin(-120^\circ) = -\frac{\sqrt{3}}{2}\phi_m$
 $\phi_z = \phi_m \sin(-240^\circ) = \frac{\sqrt{3}}{2}\phi_m$



The phasor sum of $-\phi_1$ and ϕ_2 is the resultant flux. It is clear that.

$$\text{Resultant Flux, } \phi_r = 2 \times \frac{\sqrt{3}}{2} \phi_m \cos \frac{60^\circ}{2} = 1.5 \phi_m$$

At instant-2 $wt = 30^\circ$. Therefore, the three fluxes are

$$\phi_x = \phi_m \sin 30^\circ = \frac{\phi_m}{2}$$

$$\phi_y = \phi_m \sin(90^\circ) = -\phi_m$$

$$\phi_z = \phi_m \sin(210^\circ) = \frac{\phi_m}{2}$$

The phasor sum of ϕ_x , $-\phi_y$ and ϕ_z is the resultant flux. Given by, $\phi_r = \phi_m \sin 30^\circ = \frac{\phi_m}{2}$. Phasor sum of ϕ_x and ϕ_z , $\phi'_r = 2 \times \frac{\phi_m}{2} \cos \frac{120^\circ}{2} = \frac{\phi_m}{2}$. Phasor sum of ϕ'_r and $-\phi_y$, $\phi_r = \frac{\phi_m}{2} + \phi_m = 1.5 \phi_m$

iii) At instant-3 $wt = 60^\circ$.

There, the three fluxes are given by,

$$\phi_x = \phi_m \sin 60^\circ = \phi_m \frac{\sqrt{3}}{2}$$

$$\phi_y = \phi_m \sin(60^\circ) = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_z = \phi_m \sin(-120^\circ) = 0$$

The resultant flux ϕ_r is the phasor sum of ϕ_x and $-\phi_y$.

$$\phi_r = 2 \times \frac{\sqrt{3}}{2} \phi_m \cos \frac{60^\circ}{2} = 1.5 \phi_m$$

iv) At instant-4 $wt = 90^\circ$.

Therefore, the three fluxes are given by:

$$\phi_x = \phi_m \sin 90^\circ = \phi_m$$

$$\phi_y = \phi_m \sin(-30^\circ) = -\frac{\phi_m}{2}$$

$$\phi_z = \phi_m \sin(150^\circ) = -\frac{\phi_m}{2}$$

The phasor sum of ϕ_x , $-\phi_y$ and $-\phi_z$ is the resultant flux ϕ_r .

$$\text{Phasor sum of } -\phi_x \text{ and } -\phi_y, \phi'_r = 2 \times \frac{\phi_m}{2} \cos \frac{120^\circ}{2} = \frac{\phi_m}{2}$$

$$\text{Phasor sum of } \phi'_r \text{ and } \phi_z, \phi_r = \frac{\phi_m}{2} + \phi_m = 1.5 \phi_m$$

Speed of Rotating Magnetic Field
→ The speed at which the rotating magnetic field revolves is called the synchronous speed (ms).

During this one quarter cycle, the field has rotated through 90° .

In general, for P poles the rotating field takes one revolution in $P/2$ cycles of current.


$$\therefore Cycles of current = \frac{P}{2} \times Revolutions of field$$

$$N_s = \frac{120f}{P}$$

Principle of Operation!

Consider a portion of 3- ϕ induction motor as → The operation of the motor can be explained as under:-

i) When 3- ϕ stator winding is energised from a 3- ϕ supply, a rotating magnetic field rotates around the stator under:-



ii) ($N_s = 120f/P$) Rotor rotates around the stator at synchronous speed.

iii) The rotating field passes through the air gap and cuts the rotor conductors, which are stationary. Due to

the relative speed between the rotating flux and the stationary rotor, emfs are induced in the rotor conductors. Since the rotor circuit is short-circuited, currents start flowing in the rotor conductors.

iv) The current-carrying rotor conductors are placed in the magnetic field produced by the stator. Consequently mechanical forces acts on the rotor conductors. The sum of the mechanical forces on all the rotor conductors produces a torque which tends to move the rotor in the same direction as the rotating field.

(v) The fact that rotor is urged to follow the stator field (i.e. rotor moves in the direction of stator field) can be explained by Lenz's law. According to this law, the direction of rotor currents will be such that they tend to oppose the cause producing them. Now, the cause producing the rotor currents is the relative speed between the rotating field and the stationary rotor conductors. Hence to reduce field and the stationary rotor conductors. Hence to reduce this relative speed, the rotor starts running in the same direction as that of stator field and tries to catch it.

Slip :-

The difference between the synchronous speed N_s of the rotating stator field and the actual rotor speed N_r is called slip. It is usually expressed as a percentage of synchronous speed i.e.

$$\% \text{ one slip, } s = \frac{N_s - N_r}{N_s} \times 100$$

Rotor current frequency!

The frequency of a voltage or current induced due to the relative speed between a winding and a magnetic field is given by the general formula :

$$\text{frequency} = \frac{N_p}{120}$$

Here, N_p = Relative speed b/w magnetic field and the winding.

p = Number of poles.

For a rotor speed N_r , the relative speed between the rotating flux and the rotor is $N_s - N_r$. Consequently, the rotor current frequency s' is given by;

$$s' = \frac{(N_s - N_r) p}{120}$$

$$= \frac{s N_p}{120}$$

$$\therefore s' = \frac{N_s - N_r}{N_s} \quad \left[\because s = \frac{N_s - N_r}{N_s} \right]$$

i.e. Rotor current frequency = fraction slip \times supply frequency

When the rotor is at standstill or stationary (i.e. $s=1$) the frequency of rotor current is the same as that

of supply frequency, $s' = f = 1/f = f$

(vi) As the rotor picks up speed, the relative speed b/w the rotating flux and the rotor decreases; consequently the slip s and hence rotor current frequency decreases.

Example:- 1) 6-pole, 3-phase induction motor is connected to 50 Hz supply. If it is running at 970 r.p.m. find the slip.

$$\text{S.R.P. } s = \frac{N_s - N_r}{N_s} \times 100 = \frac{1000 - 970}{1000} \times 100 = 3\% \text{ or } 0.03$$

Example-2 A 3-phase induction motor is wound for 4 poles and is supplied from 50 Hz system. Calculate (i) the synchronous speed (ii) the speed of the motor when slip is 4% and (iii) the rotor current frequency when the motor runs at 600 r.p.m.

S.R.P. \rightarrow (i) Synchronous speed, $N_s = 120 f_p = 120 \times \frac{50}{2} = 1500 \text{ r.p.m.}$

(ii) Slip, $s = \frac{N_s - N_r}{N_s} \times 100$

$$s = \frac{1500 - N_r}{1500} \times 100$$

$$N_r = 1440 \text{ r.p.m. (approx.)}$$

$$(iii) \text{ When } N_r = 600 \text{ r.p.m., } s = \frac{1500 - 600}{1500} = 0.6$$

\therefore Rotor current frequency, $s' = sf = 0.6 \times 50 = 30 \text{ Hz}$

Effect of Slip on the Rotor Current

When the rotor is stationary, $s=1$. Under these conditions, the per phase rotor emf, E_2 has a frequency equal to that of supply frequency f .

At any slips, the relative speed between stator field and the rotor is decreased.

At the same time, per phase rotor resistance R_2 , being frequency dependent, is reduced to $s R_2$.

(i) The relative speed b/w stator flux and the rotor is now only 40 r.p.m. Consequently, rotor emf / phase is reduced to $E_2 \times \frac{40}{100} = 0.04 E_2$ or $s E_2$

∴ The frequency is also reduced in the same ratio.

$$50 \times \frac{40}{1600} = 50 \times 4 \text{ or } 5f'$$

(ii) The per phase rotor resistance R_2 is likewise reduced to:

Thus at any step s ,

$$\text{Rotor emf/phase} = s E_2$$

$$\text{Rotor reactance/phase} = s X_2$$

$$\text{Rotor frequency} = sf$$

where E_2 , X_2 and f are the corresponding values at stand still.

Example: A 3-ph, 6-pole induction motor is connected to a 60 Hz supply. The voltage induced in the rotor bars is $40V$ when the rotor is at stand still. Calculate the voltage and frequency induced in the rotor bars at 300 r.p.m.

$$\text{S.P.D.} = \frac{120f}{P} = 120 \times 60/6 = 1200 \text{ r.p.m}$$

$$\text{Slip, } s = \frac{n_{\text{M}} - n}{n_s} = \frac{1200 - 300}{1200} = \frac{3}{4}$$

corresponding to this slip, we have,

$$\text{Induced voltage} = 4Xs = 4 \times 3/4 = 3V$$

$$\text{Frequency} = s n_s = 60 \times \frac{3}{4} = 45 \text{ Hz}$$

Starting Torque (T_s)

$$E_2 = \text{Rotor emf per phase at stand still}$$

$$X_2 = \text{Rotor reactance per phase at stand still}$$

$$R_2 = \text{Rotor resistance per phase}$$

$$\text{Rotor impedance/phase, } Z_2 = \sqrt{R_2^2 + X_2^2}$$

$$\text{Rotor current/phase, } I_2 = \frac{E_2}{Z_2} = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

$$\text{Rotor P.E. const} = \frac{R_2}{Z_2} = \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

$$\text{Starting torque, } T_s = k E_2 I_2 \cos \theta_2$$

$$= \frac{k E_2^2 R_2}{R_2^2 + X_2^2} \times \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

$$\therefore T_s = \frac{k R_2}{R_2^2 + X_2^2} = \frac{k R_2}{R_2^2 + R_2^2} = \frac{k R_2}{2R_2^2} = \frac{k}{2} \quad (1)$$

Differentiating eqn (1) w.r.t R_2 and equating the result to zero, we get

$$\frac{d T_s}{d R_2} = k \frac{d}{d R_2} \left(\frac{R_2}{R_2^2 + R_2^2} \right) = 0$$

$$= \frac{(R_2^2 + R_2^2) \cdot 1 - R_2 \cdot 2R_2}{(R_2^2 + R_2^2)^2} = 0$$

$$= R_2^2 + R_2^2 - 2R_2^2 = 0$$

$$= R_2^2 - R_2^2 = 0$$

$$\Rightarrow R_2^2 = R_2^2$$

$$\therefore R_2 = R_2$$

Effect of change of supply voltage

$$T_s = \frac{k E^2 R_2}{R_2^2 + R_2^2}$$

Since $E_2 \propto \text{Supply voltage V}$.

$$\therefore T_s = \frac{k_2 v^2 R_2}{R_2^2 + R_2^2}$$

Starting Torque of 3-ph Induction Motors:

The rotor circuit of an induction motor has low power factor and high inductance.

At starting, the rotor frequency is equal to the static frequency (i.e. 50 Hz) so that rotor reactance is large compared with rotor resistance.

Therefore, rotor current lags that rotor emf by a large angle, the power factor is low and consequently the starting torque is small.

square-law motor

> squirrel cage motors have starting torque of 1.5 to 2 times the full-load value with starting current of 5 to 9 times the full-load current.

ii) wound rotor motors:-

> By inserting the proper value of external resistance (so that $R_2 = X_2$), max starting torque can be obtained.

> As the motor accelerates, the external resistance is gradually cut out until the rotor circuit is short-circuited on itself for running conditions.

Torque under running conditions:

Let the rotor at standstill have perphase induced emf. E_2 , reactance X_2 and resistance R_2 . Then under running conditions at slip's,

$$\text{Rotor emf}/\text{phase}, E_2' = sE_2$$

Max torque under running conditions:

$$T_r = \frac{k_b s R_2}{R_2^2 + s^2 X_2^2} \quad \text{--- (1)}$$

In order to find the value of rotor resistance that gives maximum torque under running conditions, differentiate eqn (i) w.r.t 's' and equate the result to zero i.e.

$$\frac{d T_r}{ds} = k_b \left\{ \frac{d}{ds} \left(\frac{s R_2}{R_2^2 + s^2 X_2^2} \right) \right\} = 0$$

$$= \left\{ \left(R_2^2 + s^2 X_2^2 \right) \frac{d R_2}{ds} R_2 - k_b s R_2 \frac{d}{ds} (R_2^2 + s^2 X_2^2) \right\}$$

$$= \left\{ (R_2^2 + s^2 X_2^2) \frac{R_2}{R_2^2 + s^2 X_2^2} - k_b s R_2 (0 + 2s X_2^2) \right\} = 0$$

$$= k_b R_2 [(R_2^2 + s^2 X_2^2) - (2s^2 X_2^2)] = 0$$

$$\Rightarrow R_2^2 = s^2 X_2^2$$

$$\Rightarrow \boxed{R_2 = s X_2}$$

thus for max torque (T_M) under running conditions:

$$T_r \propto \frac{1}{R_2^2 + s^2 X_2^2} \quad \text{From eqn (1) above}$$

for maximum torque, $R_2 = s X_2$ putting $R_2 = s X_2$ in the above expression, the max torque T_M is given by:-

$$T_M \propto \frac{1}{s^2 X_2^2}$$

Slip corresponding to maximum torque, $s = \frac{R_2}{X_2}$.

It can be shown that;

$$T_M = \frac{3}{2} \times \frac{R_2^2}{s^2 X_2^2} N_p = \frac{3}{2} \pi f R_p s$$

It is evident from the above equations that:


> The value of rotor resistance does not alter the value of the maximum torque but it only changes the value of the slip at which it occurs.

> The max torque varies inversely as the standstill reactance. Therefore, it should be kept as small as possible.

> The max torque varies directly with the square of the applied voltage.

ii) To obtain max torque at starting (s=1), the rotor resistance must be made equal to rotor reactance at standstill.

Torque-slip characteristics:-



The following points may be noted carefully:

> At $s=0$, T_{r0} so that torque-slip curve starts from the origin.

> At normal speed, s_{N_p} is small so that $s X_2$ is negligible as compared to R_2 .

$$\frac{T_r}{s} \propto \frac{1}{s^2 X_2^2} \rightarrow \text{as } R_2 \text{ is constant.}$$

Hence torque-slip curve is a straight line from zero slip to a slip that corresponds to full-load.

Full-load starting and max. torques:

$$T_f \propto \frac{R_2}{R_2^2 + (sR_2)^2}$$

$$T_f \propto \frac{R_2}{R_2^2 + R_2^2}$$

$$T_f \propto \frac{1}{2R_2}$$

Note that it corresponds to full-load slip.

s_f :

$$\frac{T_f}{T_s} = \frac{s_f}{2sR_2/R_2}$$

Dividing the numerator and denominator on R.H.S by R_2^2 , we get

$$\frac{T_f}{T_s} = \frac{(R_2/s)^2 + s^2}{2s(R_2/s)^2} = \frac{s^2 + s^2}{2s}$$

Where, $a = \frac{R_2}{sR_2} = \frac{R_2}{2sR_2} = \text{Standstill rotor resistance/phase}$

$$\therefore \frac{T_f}{T_s} = \frac{a^2 + 1}{2a}$$

Dividing the numerator and denominator on R.H.S by R_2^2 , we get

$$\frac{T_f}{T_s} = \frac{(R_2/s)^2 + 1}{2(R_2/s)^2} = \frac{a^2 + 1}{2a}$$

Where $a = \frac{R_2}{sR_2} = \frac{R_2}{2sR_2} = \text{Standstill rotor resistance/phase}$

Speed regulation of induction motor:-



$$\% \text{age speed regulation} = \frac{n_f - n_{f.L}}{n_{f.L}} \times 100$$

Where, n_0 = no-load speed of the motor

$n_{f.L}$ = full-load speed of the motor

Power factor of induction motor:-

$$\text{power factor, } \cos\phi = \frac{\text{Active component of current (I}_{\text{act}})}{\text{Total current (I)}}$$



Production Motor Torque:
The mechanical power P available from any electric motor can be expressed as:-

$$P = \frac{2\pi N}{60} P_M$$

Here, N = speed of the motor in R.P.M

P_M = torque developed in N.M

$$\therefore T = \frac{60}{2\pi} \frac{P}{N} = 9.55 \frac{P}{N} \text{ N.M}$$

If the gross output of the motor of an induction motor is P_M and its speed is N R.P.M, then gross torque T_g developed is given by:-

$$T_g = 9.55 \frac{P_M}{N} \text{ N.M}$$

$$\text{Similarly } T_h = 9.55 \frac{P_{out}}{N} \text{ N.M}$$

Note:- Since windage and friction loss is small, $T_g = T_M$. This assumption leads to any significant error.

Rotor output:-

If T_g newton-metre is the gross torque developed and N R.P.M is the speed of the rotor, then,

$$\text{Gross rotor output} = \frac{2\pi NT_g}{60} \text{ watts}$$

If there were no copper losses in the rotor, the output would equal rotor input and the rotor would run at synchronous speed N_s .

$$\therefore \text{Rotor Input} = \frac{\partial \pi N_L T}{60} \text{ watts}$$

$$\therefore \text{Rotor Cu Loss} = \text{Rotor Input} - \text{Rotor Output}$$

$$= \frac{\partial \pi T}{60} (N_L \cdot \pi)$$

$$\frac{\text{Rotor Cu Loss}}{\text{Rotor Input}} = \frac{N_L \cdot \pi}{N_L} = \pi$$

$$\therefore \text{Rotor Cu Loss} = \pi \times \text{Rotor Input}$$

$$\text{By Gross rotor output, } P_H = \text{Rotor Input} - \text{Rotor Cu Loss}$$

$$P_H = \text{Rotor Input} - \text{Rotor Input}$$

$$\text{By Gross rotor output} = 1.5 = \frac{N_L}{N_S}$$

$$\frac{\text{Rotor Cu Loss}}{\text{Rotor Input}} = \frac{S}{1.5}$$

$$\frac{\text{Rotor Cu Loss}}{\text{Inress Rotor Output}} = \frac{S}{1-S}$$

$$\text{Induction Motor Torque Equation}$$

$$\text{The Gross } T_g \text{ developed by an induction motor is given by:}$$

$$T_g = \frac{\text{Rotor Input}}{\frac{60 \times N_L}{2\pi N_S}} = N_L I_m R.P.M$$

$$\text{Now, Rotor Input} = \frac{\text{Rotor Cu Loss}}{S} = \frac{3(T_2')R_2}{S}$$

Under running conditions,

$$\frac{T_2'}{S} = \frac{3E_2}{(R_2^2 + (Sx_2)^2)} = \frac{3kE_1}{\sqrt{R_2^2 + (Sx_2)^2}}$$

Where, k = Transformation ratio

$$= \frac{\text{Rotor Turns/Phase}}{\text{Stator Turns/Phase}}$$

$$\therefore \text{Rotor Input} = 3k \frac{S^2 E_2^2 R_2}{R_2^2 + (Sx_2)^2} \times \frac{1}{S}$$

$$= \frac{3S E_2^2 R_2}{R_2^2 + (Sx_2)^2} \quad \left[\text{Putting the value of } S_2 \text{ in eqn (1)} \right]$$

$$\text{Also, Rotor Input} = 3 \times \frac{S^2 k^2 E_1^2 R_2}{R_2^2 + (Sx_2)^2} \times \frac{1}{S}$$

$$\therefore T_g = \frac{\text{Rotor Input}}{\frac{R_2^2 + (Sx_2)^2}{2\pi N_L}} = \frac{3}{2\pi N_L} \times \frac{S^2 E_1^2 R_2}{R_2^2 + (Sx_2)^2} \quad [\text{In terms of } E_1]$$

Example: A 370, 60 Hz, 4-pole, star-connected induction motor having a nominal rating of 75 kW is supplied by a four-sequence. The two-wattmeter method shows a total power consumption of 76 kW and an ammeter indicates a line current of 40 A. Precise measurement gives a motor speed of 1763 rpm. The following data are known in respect of stator. Stator iron loss = 2 kW and windage and friction loss = 1.8 kW. Resistance between two stator terminals = 0.34 ohm. Calculate (i) power supplied (ii) rotor input (iii) Rotor resistances (iv) Rotor power input to stator = 70 kW and (v) Rotor copper loss.

(i) Stator resistance/phase, $R_1 = 0.34/2 = 0.17$ ohm
 (ii) Stator Cu Losses = $3 \times 2^2 R_1 \times 3 (78)^2 = 3 (78)^2 \times 0.17 = 31$ kW
 Stator iron loss = 2 kW (given)
 Stator Cu losses = 31 kW (calculated)
 Total stator losses = 31.2 + 2 = 33.2 kW

Power supplied to rotor, $P_H = 70 \times 5 = 64.9$ kW
 (iii) Rotor slip, $s = \frac{N_L - N_R}{N_L} = \frac{1800 - 1763}{1800} = 0.0205$

(iv) Rotor Cu Loss = $S^2 R_2 = 0.0205^2 \times 64.9 = 1.33$ kW
 (v) Mechanical power developed is given by $N_L \times \text{Torque}$
 $P_H = P_M + \text{Rotor Cu Loss}$
 $64.9 = P_M + 1.33 \Rightarrow P_M = 63.57$ kW

$$\text{iv) Motor efficiency, } \eta = \frac{62.3}{75} \times 100$$

$$= 89\%$$

$$\text{v) Gross torque, } T_g = 9.35 \times \frac{P}{N} = 9.35 \times \frac{62.5 \times 10^3}{1763} = 344 \text{ Nm}$$

Plugging of an Induction motor.

- Some Industrial applications, it is desired to bring the running induction motor to a rapid stop.
- This can be done by simply interchanging the two stator leads.

This process is called plugging. When we interchange two stator leads, the revolving field suddenly turns in the opposite direction to the rotor.

During the plugging period, the motor acts as a brake. It absorbs kinetic energy from the still revolving field, causing its speed to fall.

The heat power associated with the rotor is entirely dissipated as heat in the rotor.

Unfortunately, the rotor also continues to receive power from the stator which is also dissipated as heat.

Consequently, plugging produces I^2R losses in the rotor which even exceed those when the rotor is locked.

Induction Generator:


- If an induction motor whose stator windings are connected to a 3-phase line is driven by a prime mover at a speed higher than synchronous speed, it acts as a generator.
- It converts the mechanical energy it receives from the prime mover into electrical energy and electrical energy is supplied to the mains.
- Such a machine is called an induction generator or a synchronous generator.

- When speed of the induction motor exceeds the synchronous speed, the SHP becomes negative.
- Therefore, the relative motion between the rotor conductors and the rotating flux is reversed and as a result, the

directions of rotor emf and rotor currents will also be reversed.

The petrol engine is the prime-mover. As soon as the engine speed exceeds the synchronous speed, the motor becomes a generator, delivering active power P (kW) to the electrical systems to which it is connected.

- However, to create its magnetic field, the motor has to absorb reactive power Q (kVAR). This power can only come from the supply lines.



Applications of Induction Generators:

- The most important use of the principle of the induction generator lies in automatic dynamic braking.
- The motor speed exceeds the synchronous speed and the machine automatically becomes an induction generator and produces a braking torque, returning the energy of the descending load to the supply.
- Starting of 3-phase induction motor.
- The induction motor is fundamentally a transformer in which the stator is the primary and the rotor is short-circuited secondary.

→ At starting the voltage induced in the induction motor rotor is maximum ($i.e. = 1$). Since the rotor impedance is low, the rotor current is excessively large.

→ This large rotor current is reflected in the stator because of transformer action.

→ This results in high starting current (4 to 10 times the full load current) in the stator at low power factor and consequently the value of starting torque is low.

→ Because of the short duration, this value of large current does not harm the motor if the motor accelerates normally.

→ It is desirable and necessary to reduce the magnitude of stator current at starting and several methods are available for this purpose.

Methods of starting 3- ϕ Induction motors :-

→ The method to be employed in starting a given induction motor depends upon the size of the motor and the type of the motor. The common methods used to start induction motor are :-

(i) Direct-on-line starting

(ii) Star-delta starting

(iii) Auto-transformer starting

(iv) Star-delta starting

(v) Rotor resistance starting

(vi) Auto-transformer starting

(vii) Direct-on-line starting

(viii) Rotor resistance starting

(ix) Auto-transformer starting

→ Consequently, this method of starting is suitable for relatively small (upto 7.5 kW) machines.


(i) Stator resistance starting:-

→ This causes voltage drop across the resistances so that voltage available across motor terminals is reduced and hence the starting current.

→ The resistances are gradually cut out in steps from the stator circuit as the motor picks up speed.

→ When the motor attains rated speed, the resistances are completely cut out and full line voltage is applied to the motor.

→ Start: close 1-2-3
→ Next: close 4-5-6
→ Finally: close 7-8-9





→ This method suffers from two drawbacks. First, the reduced voltage applied to the motor during the starting period lowers the starting torque and hence increases the accelerating time.

→ Secondly, a lot of power is wasted in the starting resistances.

(ii) Auto-transformer starting:-

→ This method also aims at connecting the induction motor to a reduced supply after starting and then connecting it to the full voltage as the motor picks up sufficient speed.

→ The tapping on the auto-transformer is so set that when it is in the 6th, 65% of line voltage is applied to the motor.




→ At the instant of starting, the change-over switch is thrown to 'start' position.

→ This puts the auto-transformer in the 6th and thus reduced voltage is applied to the ckt.

→ For large machines, this method of starting is often used. This method can be used for both star and delta connected motors.

→ Star-Delta Starting:



→ Therefore, each stator phase gets $\frac{V}{\sqrt{3}}$ volts where V is the line voltage.

→ This reduces the starting current. When the motor picks up speed, change over switch is thrown to run position which connects the stator winding in delta.

→ Now each stator phase gets full line voltage V . The disadvantages of this method are:

a) With star connection during starting, stator phase voltage is $\frac{V}{\sqrt{3}}$. Hence the line voltages.

Consequently, starting torque is $(\frac{V}{\sqrt{3}})^2$ or $\frac{V^2}{3}$ times the value it would have with Δ -connection. That is, rather large reduction in starting torque.

b) The reduction in voltage is fixed. All small torque.

This method of starting is used for medium size machine (upto 25 h.p.)

Induction motor rating!

The name plate of 3-Φ induction motor provides the following information:

- Horse power
- Line voltage
- Line current
- Speed
- Frequency
- Temp rise.

→ The stator winding of the motor is designed for delta operation and is connected in star during the starting period.

→ When the machine is up to speed, the connections are changed to delta. The ckt arrangement for star-delta starting.

→ The six leads of the stator windings are connected to the change-over switch.

→ At the instant of starting, the change-over switch is thrown to "start" position which connects the stator winding in star.

→ Therefore, each stator phase gets $\frac{V}{\sqrt{3}}$ volts where V is the line voltage.

→ This reduces the starting current. When the motor picks up speed change over switch is thrown to run position which connects the stator winding in delta.

→ Now each stator phase gets full line voltage V . The disadvantages of this method are:

a) With star connection during starting, stator phase voltage is $\frac{V}{\sqrt{3}}$. Hence the line voltages.

Consequently, starting torque is $(\frac{V}{\sqrt{3}})^2$ or $\frac{V^2}{3}$ times the value it would have with Δ -connection. That is, rather large reduction in starting torque.

b) The reduction in voltage is fixed. All small torque.

This method of starting is used for medium size machine (upto 25 h.p.)

Induction motor rating!

The name plate of 3-Φ induction motor provides the following information:

- Horse power
- Line voltage
- Line current
- Speed
- Frequency
- Temp rise.

Author

→ All electric machines have the same basic principle of operation, special purpose machines have some features that distinguish them from conventional machines.

→ For example:- a stepper motor rotates by a specific number of degrees (e.g. 2°, 2.5°, 5° or 7.5°) in response to an input electrical signal and is widely used in digital control systems.

Stepper Motor:

→ Stepper motors are also known as stepping motors or step motors. A stepper motor is an electromagnetic motor that rotates by a specific number of degrees. In response to an input electrical signal.

→ Typical step sizes are 2°, 2.5°, 7.5° and 15°. For each electrical pulse, note that there is no continuous energy conversion (electrical to mechanical) so that the rotor does not rotate continuously as in a conventional electric power.

→ The stepper motor converts electrical pulses into programmed mechanical movement. Each revolution of the stepper motor is made up of a series of definite individual steps.

→ A step is defined as the angular rotation of the motor each time it receives the electrical pulse. Such a step control is required in many applications.

→ Each time the controller receives an input electrical signal, the paper is driven to a certain incremental distance.

→ Stepper motors are relatively cheap and simple in construction and can be made to rotate in steps in either direction.

→ These motors are excellent candidates for such applications as electric typewriters, control of floppy disc drives, numerical control of machine tools etc.


The two most popular types of stepper motors are:-

- (i) Permanent magnet (PM) stepper motor.
- (ii) Variable reluctance (VR) stepper motor.

i) PM Stepper Motor:-

→ A 2-pole, single phase permanent magnet (PM) stepper motor. When the stator is energised, the excitation torque acts on the rotor (permanent magnet).

→ The rotor will move to a position where the excitation torque is zero i.e. the rotor will be aligned (parallel) with the stator field.




→ Note that maximum torque is developed when the rotor is displaced from the stator field by either 90° or 270°; however, the torque is zero when the rotor is aligned (parallel) with the stator field.

ii) VR Stepper Motor:-

→ A 2-pole, single phase variable reluctance (VR) stepper motor. When the stator is energised, reluctance torque acts on the rotor (soft-iron material).

→ The rotor will move to a position where reluctance is minimum and air-gap flux is max. This means that rotor teeth will align with the energised stator poles.



→ With the rotor at 0° or 180°, no torque is developed. Max torque is developed at 90° and 270° which is the position where reluctance torque forces the rotor to move to position of minimum reluctance.

Step angle:

The angle through which the motor shaft rotates for each command pulse is called step angle.

It can be shown that for any PM or VR stepper motor the step angle can be found from the following two relations:

In terms of stator poles (N_s) and rotor poles (N_r), the

step angle (α) is given by:

$$\text{Step angle, } \alpha = \frac{N_s \cdot N_r}{N_s + N_r} \times 360^\circ$$

Where, α = step angle in degrees

N_s = Number of stator poles (or teeth)

N_r = Number of rotor poles (or teeth)

In terms of stator phases (n) and rotor poles (N_r), the step angle is given by:

$$\text{Step angle, } \alpha = \frac{360^\circ}{N_r}$$

Where, α = step angle in degrees

n = Number of stator phases

N_r = Number of rotor poles (or teeth)

Permanent magnet (PM) stepper motor

A permanent magnet (PM) stepper motor is a repulsion type of stepper motor.

It operates on the principle of interaction between a permanent magnet rotor and an electromagnetic field.


Construction: The stator of a PM stepper motor is composed of steel laminations and carries stator windings.

The stator windings are energised from a d.c. source to create two or more stator poles.

The rotor of the motor is a permanent magnet made of high-retentivity steel alloy.

The rotor has even no. of poles. The motor has two motor poles. The stator windings are grouped to form 2-phase

2-pole PM winding: i.e phase-A winding and phase-B winding. The phase winding terminals are brought out for d.c. excitation.



Operation: For this PM stepper motor, the number of rotor poles, $N_r=2$ and number of phases, $n=2$.

$$\therefore \text{Step angle, } \alpha = \frac{360^\circ}{N_r} = \frac{360^\circ}{2 \times 2} = 90^\circ/\text{step.}$$

When only phase-A winding is excited by a constant current as shown in Fig., stator tooth-1 becomes south pole. This makes the north pole of the PM rotor to align (parallel) with the south pole (stator tooth-1) of the stator. The rotor will remain locked in the position. Under this condition, step angle $\alpha=0^\circ$:

If phase-A winding is de-energised and phase-B winding is energised, stator tooth-2 becomes south pole. As a result, the north pole of the PM rotor (which aligns (parallel) with the south pole (stator tooth-2)) of the stator, thus the rotor has displaced 90° in the anticlockwise direction.

If phase-B winding is de-energised and phase-A is excited with reverse current it is opposite to the case in, the rotor will further rotate 90° in anticlockwise direction.

So far the rotor has completed one-half revolution. However, if we continue the appropriate switching, we can change the step angle (α) of a PM stepper motor by changing number of rotor poles (N_r) and the

number of phases (4). Thus for a 3-phase, 24-pole PM stepper motor, the step angle $\alpha = \frac{360^\circ}{4 \times 12} = \frac{360^\circ}{48} = 7.5^\circ/\text{step}$.

TRUTH TABLE

cycle	phase A	phase B	position
+	1	0	0
0	-1	1	90°
-	-1	0	180°
1	0	-1	270°
			360°

Limitations:-

The rotation, 1, -1, 0 correspond to positive, negative and zero current in a phase winding respectively,

- It is difficult to make a small PM motor with a large number of poles. Therefore, PM stepper motors are restricted to large step angles in the range of 30° to 90°.
- The PM stepper motors have high inertia because of the permanent-magnet rotor. Therefore, these motors have slow acceleration. The maximum step rate (stepping frequency) is 300 steps/second.

- The PM stepper motors have high rotational speed because of large stepping angle. Therefore, motor torque for a given power is low.

Variable-Reluctance (VR) Stepper Motor:-

- The variable-reluctance VR stepper motor operates on the same principle as the reluctance motor.
- That is, when a piece of ferromagnetic material, free to rotate, is placed in a magnetic field, torque causes the material to bring it to the position of minimum reluctance to the path of magnetic flux.

Construction:-


- The stator construction of a VR stepper motor is the same as that of a PM stepper motor. The stator pole winding are wound on each stator tooth. The motor is made of soft steel with teeth and slots.
- In the ckt, the motor is shown with fewer teeth than the stator. This ensures that only one set of

stator and rotor teeth will parallel out any given instant.

The stator has six teeth and the rotor has four teeth. The stator has three phases - A, B, C with teeth, 1 & 4, 3 & 6 & 2 & 5 respectively.

$$\text{Step angle, } \alpha = \frac{N_p - N_r}{N_p + N_r} \times 360^\circ = \frac{6 - 4}{6 + 4} \times 360^\circ = 30^\circ/\text{step}.$$

∴ the motor will turn 30° each time a pulse is applied.



Operation:-

- The position of the rotor when phase A is energised with a constant current. As long as phase A is energised the rotor will be held stationary. Note that in this condition, the rotor teeth 1 and 2 are aligned with the energised stator teeth 1 and 4. The step angle is 90°.

- When phase A is switched off and phase B is energised, the rotor will turn 30° clockwise so that the rotor teeth 3 and 4 align with the energised stator teeth 6 and 3.

- The effect of de-energising phase B and energising phase C. In this ckt, the rotor has further moved 30° clockwise so that rotor teeth 1 and 2 align with energised stator teeth 2 and 5.
- After the rotor has displaced 60° (clockwise) from its starting point, the step sequence has completed one cycle.

- The direction of rotation will be reversed if the switching sequence is in the order of A, and B. For this particular motor, applied voltage must have at least five cycles for one revolution.

Truth Table

cycle	phase			position
	A	B	C	
1	on	off	off	0°
	off	on	off	30°
	off	off	on	60°
2	on	off	off	90°
	off	on	off	120°
	off	off	on	150°
3	on	off	off	180°
	off	on	off	210°
	off	off	on	240°
4	on	off	off	270°
	off	on	off	300°
	off	off	on	330°
5	on	off	off	360°

HYBRID STEPPER MOTOR:

As the name implies, the hybrid stepper motor combines the features of the PM and the VR stepper motor. The torque developed by this motor is greater than that of the PM or VR types.

Construction:- The basic construction of a hybrid stepper motor (the stator construction) is similar to that of an VR or PM motor. However the rotor construction combines the design of the rotor of an VR and a PM stepper motor.

The rotor of a hybrid stepper motor consists of two identical stacks of soft iron as well as an axially magnetized permanent magnet.

Soft iron stacks are attached to the north and south poles of the permanent magnet.

The rotor teeth are machined on the soft iron stacks. Thus the rotor teeth on one end become the north pole and those at the other end become the south pole.

→ This motor teeth of both north and south poles are displaced in angle for the proper alignment of the rotor pole with that of the stator.

Operation:- The operating mode of the hybrid stepper motor is very similar to that of a PM or VR stepper motor.

→ The phase windings are energised in proper sequence and the rotor rotates in steps.

→ Unlike the PM or VR stepper motors, the step angle of a hybrid stepper motor is independent of the number of stator poles and depends only on the number of rotor teeth (N_R) i.e.,

$$\text{Step angle } \alpha = \frac{90^\circ}{N_R} \text{ in degrees.}$$

For a hybrid stepper motor having 5 rotor teeth, the step angle $\alpha = \frac{90^\circ}{5} = 18^\circ/\text{step}$. It means that for each change of step excitation, the rotor will turn by a step of 18° .

It may be noted that a hybrid stepper motor operates under the combined principles of the permanent magnet and variable reluctance stepper motors.

→ Therefore, the hybrid motor develops both excitation torque and reluctance torque.

Consequently, the resultant torque developed by the hybrid stepper motor is greater than that of the PM or VR stepper motor.

A hybrid stepper motor has 50 variable-reluctance motor teeth. Calculate the step angle in degrees.

$$\text{Step angle, } \alpha = \frac{90^\circ}{50} = 1.8^\circ/\text{step}$$

Application of stepper motor:-

Commercially, stepper motor are used in floppy disk drives, flatbed scanners, computer printers plotters, slot machines, image scanners, computer disc drives, intelligent lighting, camera lenses, etc. machines, and 3D printers.

Diptiranjan

A three-phase system is used to generate and transmit electric power. Three-phase voltages are raised or lowered by means of three phase transformers. A three-phase transformer can be built in two ways: i) by suitably connecting a bank of three single-phase transformers ii) by constructing a three-phase transformer on a common magnetic structure. The windings may be connected in $\text{Y}-\text{Y}$, $\Delta-\Delta$, $\text{Y}-\Delta$ or $\Delta-\text{Y}$.


i) Bank of three single-phase transformers:

- Three similar single-phase transformers can be connected to form a three-phase transformer.

The primary and secondary windings may be connected in star (Y) or delta (Δ) arrangement.

- The primary windings are connected in star and the secondary windings are connected in delta.
- The primary and secondary windings shown parallel to each other belong to the same single transformer.
- The ratio of secondary phase voltage to primary phase voltage is the phase transformation ratio k .
- Phase transformation ratio, $k = \frac{\text{Secondary phase voltage}}{\text{Primary phase voltage}}$

The phase transformation ratio is ($k = \frac{N_2}{N_1}$).



ii) Three-phase core type transformer:

- A three phase transformer can be constructed by having three primary and three secondary windings on a common magnetic circuit.
- The basic principle of a 3- ϕ transformer is in below.
- The three single-phase core type transformers, each with windings (primary and secondary) on only one leg have their unwound legs combined to provide a path for the returning flux.



The primaries as well as secondaries may be connected in star or delta.

If the primary is energised from a 3- ϕ supply, the central limb (common limb) carries the fluxes produced by the 3- ϕ primary winding.

Since the phasor sum of three primary currents at any instant is zero, the sum of three fluxes passing through the central limb must be zero.

Hence no flux exists in the central limb and it may therefore be eliminated. This modification gives a three leg core-type 3- ϕ transformer.


In this case, only two legs will act as a return path for the flux in the third leg.



Three-phase from stepper connection

➢ A three-phase transformer can be built by suitably connecting a bank of three single-phase transformers or one three-phase transformer.


➢ The primary or secondary windings may be connected in either star (Y) or delta (Δ) arrangement. The four most common connections are (i) $\text{Y}-\text{Y}$ (ii) $\Delta-\Delta$ (iii) $\text{Y}-\Delta$ and (iv) $\Delta-\text{Y}$.




(i) $[\text{Y}-\text{Y} \text{ connection}]$



(ii) $[\Delta-\Delta \text{ connection}]$



(iii) $[\text{Y}-\Delta \text{ connection}]$



$\Delta-\text{Y}$ connection

$K = \frac{\text{Primary phase voltage}}{\text{Secondary phase voltage}} = \frac{V_p}{V_s}$

➢ $\text{Y}-\text{Y}$ connection: In the $\text{Y}-\text{Y}$ connection, show in Fig. (i), 57.7% (or $\frac{1}{\sqrt{3}}$) of the line voltage is impressed upon each winding but full line current flows in each winding. Power exists in their immediate vicinity. Because of this and other disadvantages, the $\text{Y}-\text{Y}$ connection is seldom used.

➢ $\Delta-\Delta$ connection: The $\Delta-\Delta$ connection is often used for moderate voltages. An advantage of this connection is that if one transformer gets damaged or is removed from service, the remaining two can be operated in what is known as the open-delta or $\text{V}-\text{V}$ connection.

➢ $\text{Y}-\Delta$ connection: The $\text{Y}-\Delta$ connection is suitable for stepping down a high voltage. In this case, the primaries are designed for 57.7% of the high tension line voltages.

➢ $\Delta-\text{Y}$ connection: The $\Delta-\text{Y}$ connection is commonly used for stepping up to a high voltage.

Three-phase transformation with two single-phase transformers:

➢ It is possible to transform three-phase power by using two single-phase transformers.

➢ The connection of two identical single-phase transformers in open delta (or $\text{V}-\text{V}$ connection).


➢ The $\text{T}-\text{T}$ connection (or Scott connection) of two nonidentical single-phase transformers.

➢ If one transformer breaks down in a star-star connected system of three-phase transformers, three-phase power cannot be supplied until the defective transformer has been replaced or repaired.

➢ To eliminate this undesirable condition, single-phase transformers are generally connected in $\Delta-\Delta$. In this case, if one transformer breaks down, it is possible to continue supplying three-phase power with

the other two transformers because this will maintain's correct voltage and phase relations on the secondary.

however, with two transformers, the capacity of the bank is reduced to 57.7% of what it was with all three transformers in service



Applications of open-Delta or V-V connection

The V-V ckt has a no. of features that are advantages are given below by way of illustration:-

i) The ckt can be employed in an emergency situation when the one transformer in a complete A-L ckt must be removed for repair and continuity of supply is required

ii) Upon failure of the primary of secondary of one transformer of a complete A-L ckt, the system can be operated as V-V fault and can deliver 3-Φ power (with reduced capacity) to a 3-Φ load

Scout connection OR T-T connection ! -

→ although there are now no 3-phase transmission and distribution systems, a 3-phase supply is sometimes required


→ We can convert 3-phase supply into 3-phase supply through scout or T-T connection of two single-phase transformers.

→ One is called the main transformer which has a core tapped primary; the center tap being c. The primary of this transformer has N_1 turns and is connected between terminals B and C of the the 3-phase supply. The primary has N_1 turns

→ The other transformer is called shunt transformer and its primary has a N_2 turns

→ One end of the primary of the shunt transformer is connected to the common terminal c and the other end to the terminal R of the 3-Φ supply.

Feeder Transformer(T)



Applications of transformer:

i) Parallel operation of 3-phase transformers! -

ii) The secondaries of all transformers must have the same phase sequence.

iii) The phase displacement betⁿ primary and secondary line voltages must be the same for all transformers which are to be operated in parallel.

iv) The secondaries of all transformers must have the same magnitude of line voltage.

Applications of transformer:

i) Power transformers! - They are designed to operate with an almost constant load which is equal to their rating. The max efficiency is designed to be at full-load. This means that no load winding copper losses must be equal to the core losses.

ii) Distribution transformers! - These transform have variable load which is usually considerably less than the full-load rating. Therefore, there are designed to have their max efficiency at between $\frac{1}{4}$ and $\frac{3}{4}$ of full load.

iii) Auto-transformer! - An auto-transformer has only one winding and is used in cases where the ratio of turns and inductances show up or step-down differs

little from 1. For the same output and voltage ratio, on auto-transformers are used for starting induction motors and in boosters for raising the voltage of feeders.

Instrument transformers! Current and voltage trans-

formers are used to extend the range of ac instruments.


→ It is divided into two types! -

(a) Current transformers.

(b) Voltage transformers.

or Current transformers! -

→ The primary of the c.t is connected in series with the line whose current is to be measured. The secondary of the transformer is connected across a low-range (0-5A) ac ammeter. The line current (I_p) and a.c ammeter current (I_s).
 Few turns primary Current transformer



$$\Delta I_p = N_p I_s$$


$$\therefore \frac{I_p}{I_s} = \frac{N_p}{N_s}$$

→ The primary to secondary current ratio (i.e. I_p/I_s) is called c.t ratio.

$$\therefore \frac{I_p}{I_s} = C.T \text{ ratio}$$

(v) $\frac{I_p}{I_s} = I_s \times C.T \text{ ratio}$
i.e. one current (I_p) = N_p .c. ammeter reading \times C.T ratio
Thus if the reading of ac ammeter is M and the C.T ratio is $1/100$ (or $100/1$), then line current = $M/100$
 $= 100M$.

b) Potential transformer (P.T)



Secondaries potential transformer

→ A P.T is used to measure high alternating potential difference (voltage) in a power system.

→ The primary of this transformer has many turns while the secondary has few turns. It is clear a P.T is simply a well-designed step-down transformer.

→ The stepped down voltage is measured with a low range a.c voltmeter. The magnetic core of a P.T usually has a sheath-type construction for better accuracy.

→ In order to provide adequate protection to the operator one end of the secondary winding is usually grounded.

→ The primary of the P.T is connected across the high voltage line whose voltage is to be measured.

→ A low-range (0-110V) a.c voltmeter is connected across the secondary. The line voltage (V_p) and a.c voltmeter voltage (V_s) are related as:

$$\frac{V_p}{V_s} = \frac{N_p}{N_s}$$

→ The primary to secondary voltage ratio (v%) is called P.T ratio.

$$\therefore \frac{V_p}{V_s} = P.T \text{ ratio}$$

$$\therefore \frac{V_p}{V_s} = V_s \times P.T \text{ ratio}$$

Advantages of Instrument Transformers!

→ The errors, due to stray inductance and capacitance in shunts, multipliers and their lead, are eliminated
∴ we can use low-range and accurate a.c instruments.
→ The length of the connecting leads from the trans-

to the instrument is of lesser importance and load may be of small cross-sectional area.

- The measuring coil is isolated from the mains by the transformer.


By using a off-on type of transformer core, the current in a heavy-current conductor can be measured without breaking the circuit.

Tap changer:-


- In transmission and distribution systems there come voltage fluctuation (i.e. increase or decrease) involuntarily when the load on the system varies. These fluctuations can also be caused due to a voltage in the distribution system. Sometimes these variation in voltage never can result in poor unsatisfactory performance.
- In order to maintain a constant voltage or to maintain within the prescribed limits, transformer tap-changing is used.

There are two types of tap changing transformer:-

- Off load tap changing Transformer:-
- The below fig. shows the off load tap changing transformer provided with tapping (1 or 5) on the secondary winding. The position of the movable arm on the fifth slot will give fifth secondary voltage and on the fifth slot will give ninth voltage across secondary.



- during the light load period, the movable arm is placed on the first slot and with an increase in load, the movable arm is taken to a slot (2, 3, 4, 5) giving higher turns ratio so that voltage drop in the line is compensated and the op. secondary voltage is maintained.
- The disadvantage of this scheme is whenever the load changes, the load must be disconnected first from the transformer thus it is referred to as off-load tap-changing. This type of tap-changing cannot be used where continuity of the supply to the load is the main priority and it is limited where there will be one only slight change in the turns ratio.
- The drawback of off-load tap changing can be overcome by using a special arrangement to core connection to the transformer known as on-load tap-changing of the transformer. The transformer connection for on-load tap-changing is given below.



- there the coil of the winding in which tappings are to be done are divided into two parallel sections with equal taping on both sections of the coil. This forms the two winding sets as shown above.

- under normal operating conditions both the switches (S_a and S_b) are in the closed (S.C.) condition with identical tapping (i.e. 1 or 1'). As the winding is divided into parallel sections the total current will be the sum of the current in windings A and B .
- When the tappings are to be changed to maintain the continuity of the supply the tap-changing process is made in such away that at first, any one of the

winding either A or B) from the required section into be disconnected by open the respective switch.

→ Now, the tap changing is to be done to the disconnected winding. At this instant, the full load current will pass through the connected winding.

→ After changing the tapping to the disconnected winding is reconnected by closing the switch. At this moment there will be an unequal share of the load on both windings due to their different turns ratio.

Now the other winding is disconnected and tapping is to be changed which is equal to the tapping of previous disconnected winding.

→ So that there will be an equal amount of load share on both the windings.

→ In this way, the continuity of the supply is maintained and more turn ratio of tap changing can possibly compare to off-load tap changing of the transformer. Maintenance schedule of power transformer.

power transformer maintenance includes periodic electrical testing of different parameters of the transformer, being common the periodic checking of some key magnitudes such as turns ratio, excitation current, polarisation index, insulation resistance, winding resistance, leakage etc.

Blanks

Single - Phase Motors

Introduction:

Single phase motors are the most familiar of all electric motors because they are extensively used in home appliances, shops, of factories etc.

→ It is true that single-phase motors are less efficient substitute for 3- ϕ motors but 3- ϕ power is normally not available in large commercial and industrial establishments.

Types of single-phase motors:

(1) Single-phase induction motor:

a) Split-phase type

b) capacitor type

c) shaded-pole type

d) A.C. series motor/ universal motor.

e) Repulsion-start induction run-motor

f) Repulsion-induction motor

g) Synchronous motor


h) Reluctance motor

i) Hysteresis motor

j) Single-phase induction motor

→ A single phase induction motor is very similar to a 3- ϕ squirrel cage induction motor.

- It has (1) a squirrel-cage rotor identical to a 3- ϕ motor and (2) a single-phasing on the rotor.
- Unlike a 3- ϕ induction motor, cage of single-phase induction motor Rotor is not self-starting but requires some starting means.
- The single-phase stator winding produces a magnetic field that pulsates in strength in a sinusoidal manner.
- The field polarity reverse after each half cycle but the field does not rotate. Consequently, the alternating flux cannot produce rotation in a stationary squirrel cage.



However, if the rotor of a single-phase motor is rotated in one direction by some mechanical means, it will continue to run in the direction of rotation.

A matter of fact, the rotor quickly accelerates until it reaches a speed slightly below the synchronous speed.

Once the motor is running at this speed, if we continue to rotate even through single-phase current is flowing through the stator winding.

This method of starting is generally not convenient for large motors. Nor can it be employed for a motor located at some inaccessible spot.

Such a motor inherently does not develop any starting torque and, therefore, will not start to rotate if the stator-winding is connected to single-phase a.c. supply.

However, if the rotor is started by auxiliary means, the motor will quickly attain the fine speed.

This strange behavior of single-phase induction motor can be explained on the basis of double-field revolving theory.

Double-Field Revolving Theory:

The double-field revolving theory is proposed to explain this dilemma of no

torque at start and yet torque once rotated.

This theory is based on the fact that a rotating alternating sinusoidal flux ($\phi = \phi_1 \cos \omega t$) can

be represented by two revolving fluxes, each equal to one-half of the peak value of alternating flux (i.e., $\frac{\phi_m}{2}$)

and each rotating at synchronous speed ($N_s = \frac{120F}{P}$) (where F is frequency) in opposite directions.

$$\phi = \phi_1 \cos \omega t$$

Consider two rotating magnetic fluxes ϕ_1 and ϕ_2 , each of magnitude $\frac{\phi_m}{2}$ and rotating in opposite directions with angular velocity ω .

Let the two fluxes start rotating from origin at $t=0$,

After time t seconds, the angle through which the flux vectors have rotated is ωt . Resolving the flux vectors along X -axis and Y -axis, we have,

$$\text{Total } X\text{-component} = \frac{\phi_m}{2} \cos \omega t + \frac{\phi_m}{2} \cos \omega t$$

$$= \phi_m \cos \omega t$$

$$\text{Total } Y\text{-component} = \frac{\phi_m}{2} \sin \omega t - \frac{\phi_m}{2} \sin \omega t = 0$$

$$\therefore \text{Resultant flux, } \phi = \sqrt{(\phi_1 \cos \omega t)^2 + (\phi_2 \cos \omega t)^2} = \phi_m \cos \omega t$$

Thus the resultant flux vector, i.e., $\phi = \phi_m \cos \omega t$ along X -axis. Therefore an alternating field can be replaced by two rotating fields of half its amplitude, rotating in opposite directions at synchronous speed.

Making single-phase induction motor self-starting

The single-phase induction motor is not self-starting and it is undesirable to resort to mechanical spinning of the shaft or pulling a belt to start it.

To make a single-phase induction motor self-starting, we should somehow produce a revolving stator magnetic field.

This may be achieved by connecting a single-phase supply in to

two-phase supply through the use of an additional winding


When the motor attains sufficient speed the starting winding (i.e., additional winding) may be removed depending upon the type of the motor.

As a matter of fact, single-phase induction motors are classified and named according to the method employed to make them self-starting.

Split-phase motor:— Started by two phase action

through the use of an auxiliary or starting winding.

Capacitor motor:— Started by two-phase motor action through the use of an auxiliary winding and a capacitor.



↳ shaded-pole motor :- started by the action of the magnetic field produced by means of a shading core around application of the pole structure.

split-phase induction motor :-

↳ the starting torque is 1.5 to 2 times the full-load torque and the starting current is 6 to 8 times the full load current.

↳ due to their low cost, split-phase induction motors are most popular single phase motors in the market.

↳ an important characteristic of these motors is that they are essentially constant-speed motors. The speed variation is 2-5% from no-load to full load.

↳ these motors are suitable where a moderate starting torque is required and where starting periods are infrequent e.g. to drive fans (b) washing machines (c) oil burners (d) small machine tools etc.

↳ the power rating of such motors generally goes below 500W.

capacitor-start motor :-

↳ the capacitor-start motor is identical to a split-phase motor except that the starting winding has as many turns as the main winding.


↳ moreover, a capacitor is connected in series with the starting winding.

↳ the value of capacitor is so chosen that it leads I_m by about 80° (i.e. $\angle = 80^\circ$) which is considerably greater than 25° found in split-phase motor.

↳ consequently, starting torque ($T_s = k_m I_m \omega_m$) is much than that of a split-phase motor.

↳ again, the starting winding is opened by the centrifugal switch when the motor attains about 75% of synchronous speed.

↳ when the motor reaches about 75% of synchronous speed, the centrifugal switch opens the circuit of the starting winding. The motor then operates as a single-phase induction motor and continues to accelerate until reaches the normal speed.



operation :-

↳ when the two stator windings are energized from a single-phase supply, the main winding carries current while the starting winding carries zero current.

↳ since main winding is made highly inductive while the starting winding highly resistive, the current in the starting winding lags behind the main winding by a reasonable phase angle of (25° to 30°) between them.

↳ when the motor reaches about 75% of synchronous speed, the centrifugal switch opens the circuit of the starting winding. The motor then operates as a single-phase induction motor and continues to accelerate until reaches the normal speed.

characteristics:-

↳ the starting torque is 1.5 to 2 times the full-load torque and the starting current is 6 to 8 times the full load current.

↳ due to their low cost, split-phase induction motors are most popular single phase motors in the market.

↳ an important characteristic of these motors is that they are essentially constant-speed motors. The speed variation is 2-5% from no-load to full load.

↳ these motors are suitable where a moderate starting torque is required and where starting periods are infrequent e.g. to drive fans (b) washing machines (c) oil burners (d) small machine tools etc.

↳ the power rating of such motors generally goes below 500W.

capacitor-start motor :-

↳ the capacitor-start motor is identical to a split-phase motor except that the starting winding has as many turns as the main winding.

↳ moreover, a capacitor is connected in series with the starting winding.

↳ the value of capacitor is so chosen that it leads I_m by about 80° (i.e. $\angle = 80^\circ$) which is considerably greater than 25° found in split-phase motor.

↳ consequently, starting torque ($T_s = k_m I_m \omega_m$) is much than that of a split-phase motor.

↳ again, the starting winding is opened by the centrifugal switch when the motor attains about 75% of synchronous speed.

↳ the motor then operates as a single-phase induction motor and continues to accelerate until reaches the normal speed.

Characteristics


→ Although starting characteristics of a capacitor-start motor are better than those of a split-phase motor, both machines possess the same running characteristics because the main winding are identical.

→ Capacitor-start motors are used where high starting torque is required and where the starting period may be long. e.g., to drive:-


- compressors
- large fans
- pumps

→ The power rating of such motors are less towards (capacitor is used to limit the phase difference kept at $\frac{\pi}{4}$)

namely



Capacitor-Start Capacitor-Run Motor



This motor is identical to a capacitor-start motor except that

starting winding is not opened after starting, so that both the windings remain connected to the supply when running as well as at starting.

Two designs are generally used.

In one design, a single capacitor is used for both starting and running.

In the other design, two capacitor and are used in the


starting winding. The smaller capacitor is required for optimum running conditions is permanently connected in series with the starting winding. The much larger capacitor is connected in parallel with, by proportion starting and remains in the circuit during starting. The motor then runs as a single-phase induction motor.

characteristics:-

by the starting winding and the capacitor can be designed for perfect 2-phase operation at any load. The motor then produces a constant torque and not a pulsating torque as in other single-phase motors.

Because of constant torque, the motor is variation free and can be used in:-
(i) hospitals by studios and (ii) other places where precise speed is important.

Shaded-pole motor



The shaded-pole motor is very popular for ratings below 0.5 hp. (≈ 40 W) because of its extremely simple construction.

It has salient poles on the stator excited by single-phase supply and a squirrel-cage rotor a portion of each pole is surrounded by a short-circuited turn of copper called shaded coil.

Characteristics:-

The salient features of this motor are extremely simple construction and absence of centrifugal switch and absence of starting torque, efficiency and power factor are very low, these motors are only suitable for low power applications.
(i) to drive:- (a) small fans, (b) toys (c) air conditioners (d) deck fans
The power rating of such motors is upto about 30 W.